





•




A presentation by Wood.


- > Sources of contamination have been removed
- A Sub-slab Depressurization System is controlling potential vapor intrusion at Buildings 80-90
- No current risk to workers at Buildings 80-90 or at the adjoining property (59-85 Chapel St)
- Phase II data gap investigation ongoing and expected to be completing in the coming months













	 Assessment of potential vapor intrusion at Chapel Street residences Currently discussing access with owners Soil gas and groundwater sampling
	 Indoor air sampling depending on soil gas results Risk assessment after each sampling event
\triangleright	Evaluation of seasonal effects through site-wide sampling
	Soil gas, indoor air, and groundwater sampling
	Fall, Winter, and Spring sampling rounds
	Revised Phase II Comprehensive Site Assessment Report to be submitted by September 28, 2018

