Department of Planning and Development



PETITION #18-18 165 HARVARD STREET

SPECIAL PERMIT TO ALLOW A DORMER WIDER THAN 50% OF THE EXTERIOR WALL BELOW

FEBRUARY 27, 2017



Requested Relief

Special Permits per §7.3.3 of the NZO to:

Allow a dormer wider than 50% of the exterior wall below (§1.5.4.G.2 and §1.5.4.G.2.b).

Criteria to Consider


When reviewing the requested special permits the Council should consider whether:

- ➤ The specific site is an appropriate location for a single-family dwelling with dormer wider than 50% of the exterior wall below (§7.3.3.C.1).
- The proposed structure, as developed and operated, will not adversely affect the neighborhood (§7.3.3.C.2).
- ➤ The structure as proposed will not be a nuisance or serious hazard to vehicles or pedestrians (§7.3.3.C.3).
- Access to the site over streets is appropriate for the types and numbers of vehicles involved (§7.3.3.C.4).

AERIAL/GIS MAP




Site Plan



Existing Rear Elevation



Proposed Rear Elevation



Proposed Findings

- 1. The specific site is an appropriate location for a single-family dwelling with a dormer wider than 50% of the exterior wall below because dormers are featured in the neighborhood and the dormer, as proposed, will not affect the dimensional standards of an old lot in the Multi-Residence 1 zone. (§7.3.3.C.1)
- 2. The proposed structure, as developed and operated, will not adversely affect the neighborhood because the dormer is located on the rear façade not visible from the street. (§7.3.3.C.2)
- 3. The structure as proposed will not be a nuisance or serious hazard to vehicles or pedestrians. (§7.3.3.C.3)
- 4. Access to the site over streets is appropriate for the types and numbers of vehicles involved. (§7.3.3.C.4)

Proposed Conditions

- 1. Plan References.
- 2. Prior to the issuance of a building permit, the petitioner shall receive a final inspection for the addition known as Permit #12110758 in the Inspectional Services Department.
- 3. Standard Building Permit Condition.
- 4. Standard CO Condition.