#### **CITY OF NEWTON**

#### IN BOARD OF ALDERMEN

#### PUBLIC FACILITIES COMMITTEE REPORT

WEDNESDAY, MAY 8, 2013

Present: Ald. Crossley (Acting Chairman), Lennon, Albright, Gentile and Lappin

Absent: Ald. Salvucci, Danberg and Laredo

Also present: Ald. Fuller

City officials present: Joshua Morse (Interim Commissioner of Public Buildings), Alex Valcarce (Project Manager; Public Buildings), Adam Gilmore (Program Manager; Public Buildings), Ouida Young (Associate City Solicitor), and Robert Rooney (Chief Operating Officer)

#151-13 NATIONAL GRID petitioning for a grant of location to install and maintain 140'

+ of 4" gas main in COBB PLACE from the existing 4" gas main in Dwhinda

Road westerly to 36 Cobb Place. (Ward 5) [03/27/13 @ 2:21PM]

**ACTION:** APPROVED 4-0 (Gentile not voting)

**NOTE:** National Grid Permit Representative Dennis Regan presented the petition to extend a 4" gas main into Cobb Place to service 36 Cobb Place from the existing gas main in Dwinda Road. National Grid has contacted the other homeowners on Cobb Road to see if there is interest in connection to the gas supply. The public hearing was opened and no one spoke for or against the petition. Ald. Albright moved approval of the petition, which carried unanimously.

#61-13(2) CONSERVATION COMMISSION requesting that the Board of Aldermen

authorize the Mayor to abandon a portion of a flowage easement located at 288

Nevada Street. (Ward 1) [04/29/13 @ 3:34 PM]

**ACTION: APPROVED 4-0 (Gentile not voting)** 

NOTE: Attorney Michael Pierce presented the request to abandon a portion of a flowage easement located in the rear of 288 Nevada Street. Mr. Pierce's client, who owns the property at 288 Nevada Street, recently received a special permit from the Board of Aldermen to construct two 2-unit dwellings at that location. The approved plans for the special permit include a retaining wall at the rear of property. In addition, there is an existing flowage easement located in the rear of the property. The footprint of the retaining wall encroaches upon a small portion of the easement. A condition of the special permit board order requires that the small portion of the easement be abandoned before the wall can be constructed.

The Conservation Commission has reviewed the proposed abandonment and voted to provide notice to the Board of Aldermen that the portion of the easement is no longer necessary and could be abandoned. The owner of 288 Nevada Street granted the easement in the early 1980s to provide drainage should Silver Lake flood. There is no evidence that the area within the easement has ever been required to mitigate water flow because of flooding. It is very unlikely that there will ever be any flooding on the property as Silver Lake has shrunk and is on

#### PUBLIC FACILITIES COMMITTEE AGENDA

Wednesday, May 8, 2013

Page 2

its way to becoming a grassy area with no water. In addition, there is a City drain located at the back of the property, which would capture any water flow.

A plan of the showing the portion of the easement to be abandoned was attached to the agenda. Ald. Lennon moved approval of the item, which carried unanimously.

#394-12 DESIGN REVIEW COMMITTEE in accordance with §5-58 of the City of

Newton Ordinances petitioning for schematic design and site plan approval for the proposed new Fire Station 10 (755 Dedham Street) with the inclusion of a possible Wires Division building on the site of the existing Fire Station 10.

[11/06/12 @ 8:57 AM]

**ACTION:** APPROVED 5-0

**NOTE:** The public hearing for the above item was continued on November 28, 2012 at the request of the Administration. The cost for the project was much higher than anticipated and the Administration wished to evaluate the cost and determine if there needed to be changes to the site plan in order to control costs.

Public Buildings Project Manager Alex Valcarce and Architect Jeff Shaw from Dromey & Sweeney Architects provided the attached PowerPoint presentation. Since the November meeting, the project has been modified and now includes the construction of the Wires Division building as part of the Station 10 project. The original plan was to construct Station #10 and phase the Wire Division building project in after completion of the construction of Station #10.

The presentation provided a recap of the feasibility study goals and findings. Mr. Shaw reviewed the revised site plan, and schematic design with the Committee. The Design Review Committee has reviewed the revised schematic design and site plan and submitted a letter to the Board of Aldermen (attached) stating that the proposed design revisions create a more efficient plan and a smaller development footprint for both Station 10 and the Wires Building. The proposed circulation of traffic, the underground confined space training facility, and organization of the two buildings and parking remain the same as the previous site plan. The estimate for the original scope of work was over \$8 million dollars. The current estimate is \$6.78 million for both Station #10 and the Wires Building.

The size of the Wire Building was reduced in order to provide cost savings. Due to the decrease in size of the building, the equipment trailer will be stored outside but all other vehicles will be under cover. The architect reviewed the floor plan of the Wires Buildings. Storage areas in the building still exist through the use of racks to maximize storage space.

The proposed Station #10 is also smaller than first planned. The basement, which was going to hold the mechanicals for the building has been eliminated from the plan and the mechanicals rooms moved to the first floor. The architect was able to reduce the number of staircases in the station to one. The upstairs living spaces were reconfigured and a hallway was removed. There was some concern that it could create conflict between firefighters using the common room and firefighters using their bedrooms to sleep. The architect did speak with the Fire Chief regarding that issue but the Chief was not concerned, as the firefighters are careful not

#### PUBLIC FACILITIES COMMITTEE AGENDA

Wednesday, May 8, 2013

Page 3

to disturb other firefighters. The current station contains a lot of unusable space. The proposed building is much more efficient in terms of the use of space.

The reduction of the buildings allows for more green area on the site, which results in less impervious surface and better drainage. The façade of both buildings will be brick and metal panels. The color finish of the metal panels has not been determined and the architect will work with the Design Review Committee regarding the color and look of the metal panels. There was a request for the cost of doing both the station and the Wire Building in brick and the cost of doing just the station in all brick, as all of the other stations in the City are brick.

The layout of the windows and some of the other elements have not been refined but will be as the project moves forward. The Fire Chief reviewed the plans and was satisfied that the buildings would meet the Fire Department's needs.

The designs for the project include a drafting tank, which will be an alternate when the project goes out to bid. The drafting tank is a large water storage chamber built underground that provides water to test the pump devices on the engine trucks. The estimated cost of the tank is \$25,000. The water is pumped through the truck into hoses and recirculated back into the tank. The annually required testing is currently done outside of the City, as the Fire Department does not have a drafting tank. The Fire Department must find coverage when the trucks are out of the City, which can be complicated. It would be more efficient and less costly if the testing could take place in the City. Committee members requested that the Fire Chief provide information on the noise level of the testing, the hours of the testing, and estimated saving. The information will be provided at the Finance Committee meeting on May 13, 2013.

The public hearing was opened and Richard Daley, 10 Nahanton Street, asked how construction noise and dust would be managed. There is not much that can be done about construction noise but the City must abide by the noise ordinance. The general contractor will be required to control dust and debris. There will be a construction management plan in place with the hours of operation and the dust control requirements. The Public Buildings Department will meet with the neighbors of the station to advise them on the project.

Yousef Kasraie, 756 Dedham Street, asked if there was any consideration given to traffic in the area. The traffic around the station will be identical to what it is today. During the construction project, the traffic signalization for the station will be reviewed. Mr. Karaie inquired if there were any plans to install antenna tower. Mr. Valcarce responded that there were no plans to install any antenna tower. Mr. Karaie also asked if there would be any blasting during the construction of Station #10. There will no blasting associated with the project.

Irene Bobilev, 760 Dedham Street, asked what would be happening with the trees in front of the station. The trees will be removed as they block firefighters' sightline when exiting the station. However, the front of the building will be landscaped with appropriate plantings. With that, the public hearing was closed.

Committee members asked if there had been any progress in finding a site for a temporary fire station. The Administration is focusing on Nahanton Park as the site for the temporary station. The use of Nahanton Park will require approval from the State, the Parks and

Recreation Commission, the Conservation Commission, Board of Aldermen, and the Newton Conservators. There are number of steps in the approval process but the City has until February or March 2014 to complete the steps.

Ald. Gentile moved approval of the site plan and schematic design, which carried unanimously.

#### REFERRED TO PUBLIC FACILITIES AND FINANCE COMMITTEES

#174-13 <u>HIS HONOR THE MAYOR</u> requesting authorization to transfer the sum of one hundred fifty thousand dollars (\$150,000) to fund continued design of Fire Station #10 (Dedham Street) and the Wires Division from the following accounts:

Capital Stabilization – Unrestricted Capital Purposes	\$54,132
Capital Stabilization – Fire Station Renovations	\$12,880
Overlay Surplus	\$14,490
Budget Reserve	\$4,679
Public Buildings – Unexpended Salaries	\$63,819

[04/29/13 @ 6:05 PM]

**ACTION:** APPROVED 5-0

**NOTE:** The request is to transfer \$150,000 from a number of accounts to fund continued design of Station #10 and the Wires Building up to the design development phase. The Administration expects to docket an additional request to bond \$413,000 in design money to reach 100% construction drawings in July. The Administration is not requesting the full amount of design money at this time, as the bonds for 2013 have already been sold and there would be an additional cost to selling more bonds. Ald. Gentile moved approval of the request, which carried unanimously.

#### REFERRED TO PUBLIC FACILITIES AND FINANCE COMMITTEES

#311-10(A) <u>HIS HONOR THE MAYOR</u> requesting an appropriation in the amount of three million three hundred thirty-five thousand dollars (\$3,035,000) from bonded indebtedness for the purpose of funding the FY 2011 Capital Improvement Plan projects as follows: [11/29/ 10 @ 3:23 PM]

Architectural Design and Engineering/Next Scheduled Fire Station \$400,000 A-2 - HELD 6-0 \$270,000 for final design bidding and construction admin on 12/08/10

#### **ACTION:** NO ACTION NECESSARY 5-0

**NOTE:** The above request for the remaining \$270,000 for design and engineering money for the fire station is no longer necessary. Ald. Gentile moved no action necessary, which carried unanimously

#### REFERRED TO PUBLIC FACILITIES AND FINANCE COMMITTEES

#172-13 <u>HIS HONOR THE MAYOR</u> requesting authorization to appropriate the sum of

one hundred four thousand dollars (\$104,000) from the Capital Stabilization Fund (Completed Bond Financed Projects) for the purpose of covering the additional funds needed for the Lincoln Eliot Elementary School HVAC project. [04/29/13]

@ 6:06 PM]

**ACTION: APPROVED 4-0-1 (Gentile abstaining)** 

**NOTE:** Interim Public Buildings Commissioner Josh Morse presented the request for \$104,000 to fund additional costs associated with the Lincoln Eliot Elementary School univent replacement project. The Board of Aldermen approved \$250,000 for the project in June 2012. The design costs for the project were \$26,400, which left \$223,600 for construction. The low bid for the project was \$311,857. The requested \$104,000 will cover the shortage in funds and provide a 5% contingency. The funds are available to be appropriated from the Capital Stabilization Fund, as a result of realized savings from completed bonded projects.

The Public Buildings Department did look at reducing the scope of the work at the school but it would have negatively affected the heating of the school. The univents are over 60 years old and well past there useful life of 20 years. The School Department has had to cancel kindergarten classes due to failed heating equipment.

It was pointed out that there have been recent discussions about the possibility of installing air conditioning the Angier Elementary School when it is replaced. None of the elementary schools in the City are currently air-conditioned. If one school is going to be air conditioned, the City should consider air conditioning all elementary schools. As the Public Buildings Department is working on the HVAC system at Lincoln Eliot School, it might be appropriate to install air conditioning as part of the project.

Commissioner Morse explained that the additional cost to the project would be roughly \$2.5 million and would require substantial construction to run the piping for the air conditioning. The specifications for the univents include larger pipes that can provide either steam or water with future air conditioning. In addition, the Lincoln- Eliot School is scheduled for renovation in the next seven to ten years and it would be appropriate to consider air conditioning at that point.

Commissioner Morse added that it is urgent that the heating system for the school is replaced this summer. The Committee understood the need and Ald. Lennon moved approval, which carried by a vote of four in favor and one abstention.

#### REFERRED TO PUBLIC FACILITIES AND FINANCE COMMITTEES

#41-13 <u>ALD. CROSSLEY, FULLER AND SALVUCCI</u> requesting a discussion with the administration to review how the city inventories, plans for, budgets and accounts for needed smaller capital expanditures (currently set at under \$75,000), which

for needed smaller capital expenditures (currently set at under \$75,000), which are excluded from the Capital Improvement Plan (CIP); how to make these non-CIP capital maintenance items visible, and how to integrate them with the overall

planning, CIP, and budgeting processes. [01/14/13 @ 5:02 PM]

**ACTION: HELD 4-0 (Gentile not voting)** 

#### PUBLIC FACILITIES COMMITTEE AGENDA

Wednesday, May 8, 2013

**NOTE:** Commissioner of Public Buildings provided the attached raw list of Public Building's Department projects under \$75,000. The list currently contains 411 items with a total value of approximately \$3.5 million. The projects include accessibility improvements, life safety projects, electrical improvements, painting, masonry work, and a few energy related projects. There is some overlap between the Preferred Vendor Program projects and the list. There is \$150,000 in the upcoming budget to address some of the projects on the list, such as replacing the boiler in Fire Station #2 and replacing deteriorated flooring in several building. In addition, there is \$225,000 in the outside contractor line item and another \$60,000 for materials. A portion of the outside contractor funds could be used to address some of the list.

The Committee would like a one-page summary of how the Public Building Department is planning to address the projects on the list. The summary should also include how much overlap there is with the Preferred Vendor Program. The Committee needs to understand how much work there is on the list and the timeframe for completing the work. Committee members would like to discuss options on how to fund these projects, as they are important to the overall quality and maintenance of buildings. Ald. Albright moved hold for further discussion. The motion carried unanimously.

#### REFERRED TO PROGRAMS & SERV. AND PUBLIC FACILITIES COMMITTEES

#315-12 ALD. FULLER, RICE AND GENTILE of the Angier School Building

Committee providing updates and discussion on the Angier School Building project as it develops through the site plan approval process. [10-02-12 @

3:37PM]

ACTION: HELD 5-0

**NOTE:** Ald. Fuller joined the Committee to provide an update on the Angier School Building Project. There have been recent discussions regarding the cooling needs and available cooling systems for the elementary schools. If the Angier School is to be air conditioned, the decision needs to be made sooner rather than later.

A recent meeting of the Angier Working Group included members of the School Committee, the Owner's Project Manager, the architect, the Public Buildings Commission, the School Department's Director of Operations, the Design Review Committee Chairman, the Chief Financial Officer, the Chief Operating Officer and other City officials met recently to discuss cooling of the Angier School. The architect and owner's project manager spoke to the different options to control climate at the Angier School. Every system would provide full air conditioning of the library and administrative offices. There are three possibilities to control climate in the classrooms: 1) operational windows, 2) a dehumidification system and 3) full air conditioning. The Angier Design Team also provided cost estimates to provide a dehumidification system versus full air conditioning. The cost of the base system alone would be about \$2.1 million. A dehumidification system would add approximately \$200,000 to the base system, and a full air conditioning system would add an additional \$400,000 to air condition all the classrooms. There would be extra annual operating costs to run the cooling system.

#### PUBLIC FACILITIES COMMITTEE AGENDA

Wednesday, May 8, 2013

Page 7

There was concern that the meeting group was not representative enough to complete the technical discussion and should be informed by members of the Design Review Committee and people with expertise in climate control systems.

The decision to put air conditioning in the elementary schools is a major policy decision with far reaching implications. It was pointed out that the decision to air condition the one elementary school influences all elementary schools. It is important that there is a level of parity between the elementary schools. There was concern that the Angier School Building Committee would be making the decision regarding air conditioning because they will be voting on whether the Angier is air-conditioned. It is ultimately the Mayor's decision whether it is appropriate to include air conditioning in the Angier School Building Project and therefore, in each upcoming elementary school replacement or renovation.

The School Committee and the Board of Aldermen will be meeting on June 3, 2013 to receive an update on the project. It would be appropriate to have a full discussion on the matter of air conditioning the elementary schools. It was request that the Public Buildings Commissioner or Project Manager inform the Owner's Project Manager that the Angier School Building Committee should not take any vote related to air conditioning the Angier School until after the June 3, 2013 meeting.

A motion to hold was made and carried by a vote of five in favor and none opposed.

Respectfully submitted,

Deborah Crossley, Chairman

# Newton Fire Station #10

Site Plan Review 8 May 2013

Principal-in-charge Jeff Shaw, AIA

#### Feasibility Study Recap: Study Goals:

- The study was limited to the existing facilities: HQ, Station 3 & Wires Division (Newton Centre), Station 10 (Oak Hill).
- Determine suitability of each Existing Station for modern firefighting needs
- Review Code compliance
- Study the Space Needs for each facility over the next 20 years



Headquarters



Station 3 & Wires Division



Station 10

#### Feasibility Study Recap: Recommendations

Relocate Wires Division to Station 10 property due to large lot size and use compatibility

Construct Station 10 with Wires Building behind

Construct a combined facility for Station 3 & HQ in phased operation

#### #394-12


### Fire Station #10 Space Needs Fire Station Phase 1:

	Current	Needed
Personnel		
<ul> <li>Captain/Lieutenant</li> </ul>	4 (1/shift)	4 (1/shift)
<ul> <li>Firefighters</li> </ul>	12 (3/shift)	12 (3/shift)
<ul> <li>Parking, Public</li> </ul>	0	1
• Parking, Staff	20+	8
		(incl. shift change)
<ul> <li>Front Line Apparatus</li> </ul>		1
<ul> <li>Reserve Apparatus</li> </ul>		
		(ladder or engine)

### Fire Station Phase 1: Wire Division Space Needs

Current		1	5	0 0	5	1 5	4
	Personnel	<ul> <li>Superintendent (at HQ)</li> </ul>	• Staff	<ul> <li>Parking, Public</li> </ul>	• Parking, Staff	<ul> <li>Vehicles Under Cover</li> </ul>	• Vehicles Outside


## Oak Hill Neighborhood



Donham & Sweeney

ARCHITECTS





### Donham & Sweeney























ALL UTILTIY AND ROAD WORK SHALL COMPLY WITH CITY OF NEWTON REQUIREMENTS.


Donham & Sweeney ARCHITECTS

STATION 10 Approved Proposal DRC 10/18/2012 SITE SECTION



Donham & Sweeney ARCHITECTS

Revised Proposal SITE SECTION STATION 10



#394-12

Donham & Sweeney Approved Proposal DRC 10/18/2012 SITE ELEVATIONS STATION 10

2 PROPOSED SITE ELEVATION SCALE: NTS

EXISTING SITE ELEVATION SCALE. NTS

C EXSTINGBLOG

### ARCHITECTS

Donham & Sweeney

STATION 10
Revised Proposal
SITE ELEVATIONS


#394-12

2 PROPOSED SITE ELEVATION SCALE NTS





SCALE: NTS

C EXSTING BLDG



#394-12






### ARCHITECTS

### Donham & Sweeney

Approved Proposal DRC 10/18/2012 ELEVATIONS STATION 10


#394-12


2 NORTHWEST ELEVATION SCALE: 316"-1"



NORTHEAST ELEVATION.


SOUTHEAST ELEVATION.






Revised Proposal ELEVATIONS


STATION 10






WIRE DIVISION
Revised Proposal
FIRST FLOOR PLAN

SPOOL TRAILER



### Donham & Sweeney ARCHITECTS

#### WIRES DIVISION ELEVATIONS



## Newton Fire Station #10

Site Plan Review 8 May 2013

Jeff Shaw, AIA Principal-in-charge

### #394-

Donham & Sweeney

ARCHITECTS

**GENERAL NOTES** Newton, MA 02459 Newton Fire Station 10 - Oak Hill

00.0011:150

### Scale: As Shown Drawn by: PGC issue date REV.1 11-19









### Meyerm 207 586 6000 other theod The Chinach Rd H I T E C T S Harrison on MA H A F POLARIS POLARIS Donham & Sweeney



# OPERATIONS AND MAINTENANCE PLAN

# EROSION CONTROLS:

No excavation is allowed within any City right-of-way befieren November 15th and ppin 15th. If a mempapin, paiss of there are extended riccumstances, applicant may seek permission for such work from the City DPW Commissioner via the City Engineer. If permission is appended, special construction standards will be applied. Applicant or Applicant's representative must contact the City of Newton Engineering Department prior to start of work for confriction.

Miscellaneous GENERAL NOTES

The Contractor needs to notify the Engineering Division 48-hours in advance and schedule on appointment to have the drainage system, writer & sewer services inspected. The system & utilities must be fully exposed for the inspector. Once the inspector is satisfied, the system & utilities may then be back-filled.

All freech excendion contractors shall comply with Massachusette General Laws Chapter 824. Trench Excustors Softley Requirements, to protect the general public from mountaincrized access to unattended trenches. A Trench Excustors Permit is required and shall be the Contractor's responsibility. This applies to all trenches on public and private property.

- 1. INSTALL EROSION CONTROLS PRIOR TO COMMENCEMENT OF THE LEARINMORK OPERALTINS.
  2. INSTALL EROSION CONTROLS IN ACCORDANCE WITH CITY OF NEWTON PERALT AND MACCORDANCE WITH THE DEFILIS.
  3. INSPECT EROSION CONTROLS IMMEDIATELY AFTER EACH STORM AND REMOVE ACCOUNTANTED SEGMENT AS RECOMED. A. REPLACE DAMAGED EROSION CONTROLS AS REQUIRED. DEEP SUMP CATCH BASINS AND STORMCEPTORS.
- 1. CATCH BESINS AND STORMEDFORMS ARE TO BE CLEANED WHEN SEDMENT BUILDUP IS SENSOR ARE TO BE CLEANED WHEN SECRED ANNUALLY.
  2. BESING ARE TO BE CLEANED FOUR TIMES PER YEAR AND INSPECTED ANNUALLY.
  3. DESCRIPTION OF CLEANED FOUR TIMES PER YEAR AND INSPECTED ANNUALLY.
  3. DESCRIPTION OF FEDERAL GUIDELINES AND RECOLUTIONS.
  1. LUCKAL, STAFF AND FEDERAL GUIDELINES AND RECOLUTIONS.

## PARKING AREA SURFACE

- RECULARY PICK UP AND REMOVE LITTER FROM THE PARKING LOT, LANDSCAPED ISLANDS AND PETWIETER LANDSCAPED AREAS AND DETBYTION AREAS.
   THE DARKING AREA IS UP SE SINETY BI-AMMULLIY AT A MINIMUM, AT LESST ONCE IN THE SPRING AND ONCE IN THE FALL.

## LEACHING BASIN:

## OWNER INFORMATION:

1. All new sewer service and/or structures shall be pressure tested or video-laped after final institution is complete. Method or final inspection shall be determined solely by the construction size-action than the City Engineering Division. All sewer manhotes shall be wacuum tested in nocedoner to the City's Construction Standards & Apecifications. The sewer service will NOT be accepted until one of the two methods stated above is completed. All testing MISTs he minessed by a representative of the Engineering Division. A Cartificate of Occupancy will not be recommended until this test is completed and a written report is neceived by the City Engineer.

The service connection from the proposed building to the existing sewer manhole will have to be covered by the control of the

The existing water & sewices shall be cut and capped at the main and be completes removed from the site and properly back filled. The Engineering Division must inspect this work, failure to having this work inspected my result in the delay of issuance of the Utility Connection Permit.

Sewer

The Contractor will have to apply for a Street Opening & Utilities Connection Permits as well as a sidewalk-crossing permit with the Newton DPW. Prior to Occupancy permit being issued, on As-Bald Plan shall be submitted to the Uniquenting bission in both agital formed and in hard copy. The plan should show Unites and final grades, any ecsements and final grading.

Demolition


1. THE OWNER OF THE SITE SHALL BE THE CITY OF NEWTON, ACTING THROUGH ITS FIRE DEPARTMENT.



### Newton Fire Station 10 - Oak Hill Newton, MA 02459 Project munder 1106.00 EXISTING CONDITIONS PLAN

Scale: As Shown
Drawn by: PGC
sissue date
DRC Set 10-31-12
REV.1 11-19-12


#394-12




Newton Fire Station 10 - Oak Hill Newton, MA 02459 payer number 110600 PROPOSED DEMOLITION PLAN


20-16-10 #3994-12












POLARIS

Consultants | AR CHITECTS | AR Chines have believed but the polariscon com | Consultants |

Newton, MA 02459 Newton, MA 02459

DETAIL SHEET TWO

State: As Shown Trees by 100 community 100 c





Design Review Committee
PUBLIC BUILDINGS DEPARTMENT

Arthur Cohen, Chairman Joshua R. Morse, Interim Commissioner Telephone (617) 796-1600 FAX (617) 796-1601

TTY: (617) 796-1089 52 Elliot Street Newton Highlands, MA 02461-1605

Setti D. Warren Mayor

> Honorable Board of Aldermen City of Newton 1000 Commonwealth Avenue Newton Centre, MA 02459

Date:

25 April 20123

RE:

Fire Station 10 and Wires Division

SUBJECT:

Revised 100% Schematic Design and Site Plan Review

Honorable Board:

On Wednesday, 24 April 2013 the Design Review Committee (DRC) met and reviewed the revised Schematic Design and proposed site plans for Fire Station 10 and Wires Division building dated 24 April 2013 as submitted by Donham & Sweeney Architects on behalf of the Public Buildings Department and Newton Fire Department. The project had been previously reviewed and approved by the DRC on 18, October 2012. Since that time the project has been modified to include the construction of the Wires Division building as part of the Station 10 Project.

Schematic Design and Site Plan Approval

The Design Review Committee has determined that the schematic design and site plans herein submitted continue to be appropriate and consistent with the concepts, space needs program, and recommendations identified in the Feasibility Study. The Fire Department has indicated to the DRC that the revised proposed layouts are also consistent with the Department's preferred solution and address the needs they have identified. The revised site plan organization and circulation remain essentially unchanged from the previously approved plan. The Station 10 and Wires Building layouts, footprints and massing have been further refined resulting in a more efficient plan and smaller development footprint. The Committee believes that the proposed design revisions provide improvements to the previously approved design solution.

In accordance with Section 5-58 of the Revised Ordinances, this letter is to petition the Board of Aldermen on behalf of the Fire Department for Site Plan Approval subject to the following as part of the Design Development Phase:

- Further study of bathroom location, entries and fixture layout.
- Study of metal panel options, materials, colors and finishes for durability and fade resistance.
- Further investigation / confirmation with DPW that existing water pump cannot be relocated.

Sincerely,

Arthur Cohen, FAIA, LEED AP Chair Design Review Committee

Attentihen

CC: Design Review Committee Members
Joshua Morse, Interim Commissioner of Public Buildings
Robert Rooney, Chief Operating Officer
Maureen Lemieux, Chief Financial Officer
Chief Bruce Proia NFD

Building	Asset Type	Asset Name	Recommendation	Cos	st
B011 - Newton	Accessibilit	Daulina	Restripe the accessible parking space so that the access		
Corner Library	y Item	Parking	aisle is 96" wide.	\$	100
B032-Lower Falls Community Center	Wall group	Wall group 1	Repair, grout pipe penetration holes(1ls)	\$	179
B003-Newton Senior Center	Accessibilit y Item	General Exterior	Provide an accessible table on the outdoor patio.	\$	300
B017- Newton Free Library	Accessibilit v Item	Parking	Restripe pavement markings for accessible spaces to have a striped access aisle.	\$	300
B031-Emmerson Community Center	Accessibilit y Item	Parking	Restripe pavement markings to provide an accessible parking space with access aisle.	\$	300
B028 - Jackson Homestead Museum	Other element group	Other element group 5 (rear conc stair)	Repair hairline crack at corner of rear concrete deck(1sf).	\$	369
B002-Carr Building	Flooring	Concrete Flooring	Repair wood access boards in pipe passage floor which are a tripping hazard (5Sf).	\$	428
B028 - Jackson Homestead Museum	Ceiling group	Ceiling group 2	Repair broken floor planking on first floor (5sf).	\$	428
B003-Newton Senior Center	Accessibilit y Item	Parking	Re-stripe to provide a van accessible parking space and add a sign that says "van accessible".	\$	450
B006-Fire Station #1, Newton Corner	Accessibilit y Item	Parking	Provide an accessible parking space.	\$	500
Public Buildings OPERATING BUDGET	Security Systems		\$12,500/year	\$	12,500
Police Headquarters		ust	Remove underground heating oil tank. Do with repaving parking lot	\$	16,249
Police Headquarters		electrical upgrades	Coordinate a cable tray design with IT Department to support main trunk of cabling for TER to TR closets. • Install (~10) all-weather GFI receptacles at or near exterior doorways. • Convert exterior lighting to LED to reduce frequency of maintenance and improve efficiencies.	\$	40,809
Senior Center	structural		Repair cracks at boiler room foundation wall; Patch spalling concrete at egress strair; Repair cracks at exterior top of foundation wall.	\$	12,131
Pelligrini pk fieldhouse	finishes		Renovate kitchen cabinets and plumbing, venting, etc. (300sf, 30lf cabinets)•Install grab bars at toilet (1ea).	\$	21,071
Burr Park Field house	interior finishes		Clean up and dispose of all old junk in the basement (1600sf). Repair cracks in foundation wall (1800sf). Remove terra cotta basement walls(1000sf). Replace damage acoustical ceiling tiles on first floor (10%=200sf). Remove balance of basement ceiling and replace with new fire rated drywall(1600sf) Clean, patch concrete floors (1600sf). Install fire rated door to basement(1ea). Repair remaining doors and replace door hardware with ADA-compliant hardware (5 ea).	\$	42,218
Crystal Lake		Structural	Remove loose concrete from spalled porch awnings to prevent concrete from falling on a person below and patch overhead concrete. Determine immediate need.	\$	28,629

Newton Free Library		Building Envelope	Clean and stain cedar roof soffit at 2nd floor level (6,000 sf) to match existing stain color.Replace (1) single door w/ frame at loading dock.•Replace (1) double hung door w/	\$ 34,485
Jackson Homestead	Electrical		frame at loading dock.  Update fire/smoke alarm horn strobes and beacons to ADA- compliant units. Rewire entire Telcom infrastructure to BICSI code and secure site utilities to the building. Add additional duplex receptacle to each office location (~20 locations) to address extensive use of power strips and extension cords. Some will be addressed in Archive	\$ 43,617
Jackson Homestead	Roof		Remove rolled roofing on shed and install new roofing (400sf).	\$ 15,807
Jackson Homestead			Foundatn repairsRepair, point, tuck, water lock paint foundation wall. Exterior waterproofing is required to prevent ground water from seeping in through the stone foundation(1700sf). Remove basement carpet. Repair level concrete slab. Replace with epoxy floor or tile until water infiltration problem is corrected (1400sf)	\$ 25,667
Senior Center	Finishes		Repair plaster ceilings (5%=2400sf). • Repair walls that have water damage from windows and roof leaks(10%=2100sf). • Replace kitchen cabinetry and countertops (500sf).	\$ 41,401
Nahanton Park Field House	Mechanical		Provide control dampers at furnace for combustion air openings. Provide a new filter. Fix ductwork to ensure better seal at filter/return plenum.	\$ 3,807
Fire Station #1	Stairs		Make minor repairs to stairs (45r).	\$ 22,139
Bulloughs Pond Shelter	Windows and Doors		Remove and replace all windows (4ea). Remove, repaint and reinstall security screens on all windows (4ea).	\$ 11,580
Police Headquarters	Stairs	Stairs	Replace all rubber stair treads (108 risers).	\$ 22,239
Public Buildings	Building Envelope		Repair damaged metal siding and repaint. Remove and replace entry pad at front overhead door and add bollards to protect door jambs.	\$ 22,405
Nahanton Park Field House	Electrical		Add (2) exterior all-weather GFI receptacles around the perimeter of the building. •Add egress lighting fixtures (2) units to men's and women's bathrooms and replace battery back-up units (4) in all other Egress lighting fixtures. •Install audible fire alarm horns and beacons in toilets to meet ADA requirements (2ea). •Upgrade interior lighting to Super T-8 flourescent fixtures to improve energy efficiency.	\$ 13,879
B010-Police Annex	Accessibilit y Item	Exterior	Since there is only one accessible parking space, restripe and provide signage for a "van accessible" parking space; Install code-compliant handrail extensions at the bottom of the entry stairs.	\$ 500
B028 - Jackson Homestead Museum	Wall group	Wall group 1	Repair minor wood shingles at rear of 1 story buildging(1sf) and touch up painting in the areapir area	\$ 535
B005-Crafts St DPW Operating Ctr (Stable)	Flooring	Flooring group 3 (wood)	Re-nail flooring as required, install safety railing around 5x5 opening in floor (1ea).	\$ 550

B005-Crafts St DPW	1				
	Accessibilit	Dorleina	Provide a "van accessible" parking space including signage;		
Operating Ctr	y Item	Parking	Restripe accessible space to include a 5ft. access aisle.	\$	550
(Stable)			Denois descend (seissing floor boards on othic and first	Ą	330
B011 - Newton	Floor deck	Floor deck group 1	Repair damaged/missing floor boards on attic and first	\$	564
Corner Library	group		floor (66 sf)	Ą	304
B037-Winchester	Door group	Door group 2 (OH Door)	Repair pellet shot holes in middle of overhead door (1ea).	\$	622
Street Garage B028 - Jackson	Other			۲	022
		Other element group 3	Scrape and paint decking at main front entry stairs(2r,		
Homestead	element	(Main froint stair)	30sf).	\$	669
Museum	group		·	Ą	009
B034-Auburndale	Flooring	Carpet	Remove and replace carpet(100sf).	\$	677
Cove Fieldhouse				Ą	0//
B029-Crafts Street	Roof beam	D (1	Patch 8 SF of concrete joists where overhead doors have		
Garage	group	Roof beam group 2	chipped away concrete.	\$	71.4
-			,	Ş	714
B033-Albermarle	Roof beam	5 (1	Clean corrosion from open web steel roof joists in vicinity		
Fieldhouse	group	Roof beam group 1	of roof vent and repaint. (10 sq ft)	۸.	720
	0 1			\$	739
B008-Newton	Skylight				
Police	group	Skylight group 1 (dome)	Repair skylight leak (1ea).	,	750
Headquarters	8. o. b			\$	750
B027-Public			Replace weather-stripping and thresholds at exterior doors		
Buildings	Door group	Door group 1	(2ea).	_	
Department			(200).	\$	751
B006-Fire Station	Grille/diffu				
#1, Newton Corner	sser group	Grille/diffusser group 1	Clean exhaust grilles/diffusers.		
				\$	776
B034-Auburndale	Roofing	Roofing group 1	Repair downspout (1ea).	_	776
Cove Fieldhouse	group	00 1		\$	776
B043-Highlands	Wall group	Wall group 2	Repair damaged areas of exterior CMU walls as required	_	705
Fieldhouse	Ů,	0 1	(15 SF).	\$	785
B008-Newton	Accessibilit		Provide 5 percent or at least one locker that has accessible		
Police	y Item	Locker Rooms	hardware installed within reach range;		
Headquarters	,		•	\$	810
B008-Newton	Ductwork		Flex duct at electric room needs to be routed to diffuser to		
Police	group	Ductwork group 1	grille. Ductwork cannot be opened and is hanging from	_	
Headquarters	- '		ceiling.	\$	854
B035-Cabot Park	Wiring	Wiring Group 2 -	Reattach and properly secure telephone service wiring.		
Fieldhouse	group	Telephone		\$	855
Forte Park	Mechanical		Install manual damper in ventilation fans to prevent		
TOILE TUIK	TVTCCTTatricat		transfer of cold air and moisture into building.	\$	895
B040-Forte Park	Painting	Painting group 1	Paint approximately 20% of the exterior wall (200 SF).		
(Allison)	group	I amunig group I		\$	924
B040-Forte Park	Wall group	Wall group 2	Refasten clapboard siding at locations where nails are loose		
(Allison)	vvan group	** all 61 oup 2	(200sf).	\$	936
	Floor - I		Add egress lighting to Men's and Women's toilets.	\$	2,638
Forte Park	Electrical				
Forte Park	Dom.				
		Dom water			
B043-Highlands	Dom.	Dom water piping/insulation 2 - cold	Insulate cold water piping to prevent condensation.		
	Dom. water piping/insu	piping/insulation 2 - cold	Insulate cold water piping to prevent condensation.		
B043-Highlands	Dom. water piping/insu lation		Insulate cold water piping to prevent condensation.	\$	962
B043-Highlands	Dom. water piping/insu	piping/insulation 2 - cold	Insulate cold water piping to prevent condensation.  Repair ceramic tiles in bathrooms as required(5%=50sf).	\$	962

	_	T		1
B001-City Hall	Accessibilit y Item	Corridors	Reposition clock on 1rst floor or install a cane-detectable barrier around it because it projects >4" into the circulation route and is therefore a protruding object; Reposition signs in 2nd floor corridor because they reduce headroom to <80" AFF.	\$ 1,000
B006-Fire Station #1, Newton Corner	Flooring	Ceramic Tile	Repair damaged areas of ceramic tile floor (10%=60sf)	\$ 1,009
B033-Albermarle Fieldhouse	Lintels group	Lintels Summary	Clean and repaint steel lintels.	\$ 1,033
B019 - Nonantum Library	Ductwork group	Ductwork group 1	Remove abandoned flexible ductwork from dryer vent and insulate and seal opening to outside window.	\$ 1,058
B032-Lower Falls Community Center	Skylight group	Skylight group 1	Repair leaky skylight (1ea).	\$ 1,088
B036-Nahanton Park Fieldhouse	Window group	Window Group 1 - Glass Block	Repair glass blocks in glass block exterior windows that are cracked (2ls).	\$ 1,088
B037-Winchester Street Garage	Flooring	Flooring group 3 (Attic)	Replace temporary wood plywood in the attic over the floor opening with structural framing and plywood. (50sf).	\$ 1,100
B001-City Hall	Accessibilit y Item	Parking	Add new "Van Accessible" parking signage at van accessible parking spaces.	\$ 1,100
B003-Newton Senior Center	Bearing wall group	Bearing wall group 1	Repair roof flashing (10 SF) and repoint brick at area where water infiltration is evident (100 SF).	\$ 1,127
B037-Winchester Street Garage	Lintels group	Lintels group 1	Scrape, prepare surface of lintels for paint(30lf).	\$ 1,143
B022-Pelligrini Park Field House	Ceiling group	Acoustical Tile	Replace acoustical ceiling tiles damaged from roof leak(50sf).	\$ 1,145
B037-Winchester Street Garage	Element group	Element group 1 (wood planks)	Repair damaged areas of wood plank siding (100sf).	\$ 1,216
B018-Waban Library	Painting group	Painting group 1	Scrape, prepare surface and paint woodwork at gable ends(150sf).	\$ 1,228
B035-Cabot Park Fieldhouse	Int. Wall group	Interior Walls	Repair and patch scattered areas of interior wall damage (10%=200sf).	\$ 1,243
B033-Albermarle Fieldhouse	Column Group Summary	Column Group Summary 1	Clean base of the two exterior steel columns of all corrosion and prepare the exposed surfaces of the steel columns and coat with a high quality paint system. (2 cols 32 sq ft).	\$ 1,243
B033-Albermarle Fieldhouse	Ext receptacles group	Ext receptacles group 1	Add Exterior GFI electrical power receptacles at front and rear entrance (2ea).	\$ 1,243
B034-Auburndale Cove Fieldhouse	Ext receptacles group	Ext receptacles group 1	Add (2) all-weather GFI electrical power receptacles adjacent to building entrances.	\$ 1,243
B036-Nahanton Park Fieldhouse	Flooring	Flooring 2 - Concrete	Scrape, prepare surface and recoat bathroom floors with a non-slip epoxy floor finish (200sf).	\$ 1,243
B036-Nahanton Park Fieldhouse	Int receptacles group	Int receptacles group 1	Replace 10% worn power receptacles and add GFI receptacles to the Men's and Women's toilets (2ea).	\$ 1,243
B035-Cabot Park Fieldhouse	Int receptacles group	Int receptacles group 1	Add GFI electrical power receptacles to the men's and women's toilet rooms.	\$ 1,243
B035-Cabot Park Fieldhouse	Ext	Ext receptacles group 1	Add (2) all-weather GFI receptacles on the outside perimeter of the building.	\$ 1,243

B043-Highlands	Ceiling		Repair damaged areas of interior of concrete ceiling as		
=	_	Ceiling group 1		\$	1,243
Fieldhouse B040-Forte Park	group		required (100 SF).	۲	1,243
	Element	Element group 1	Repair ornamental portion of columns, prepare surfaces,	ے ا	1 270
(Allison)	group		and repaint (2 EA).	\$	1,270
B042-Upper Falls Fieldhouse	Door group	Door group 1	Replace single hung door and add security door grill (1 EA).	\$	1,270
B028 - Jackson					
Homestead	Ceiling	Ceiling group 4	Repair plaster ceiling in attic and repaint. (300sf)		
Museum	group	8 8 2 mp	The part of the pa	\$	1,283
	Other			<u> </u>	_,
B040-Forte Park	element	Ramp	Repair exterior concrete ramp apron (100sf).		
(Allison)		Namp	hepail exterior concrete ramp apron (10031).	\$	1,316
B015 - Elliot St.	group			7	1,310
	Flooring	Carpet Flooring	Remove carpet and replace with entry mat. (80sf).	\$	1,358
Operations Center	Callina			ې	1,336
B003-Newton	Ceiling	Acoustical Tile Ceiling	Repair and replace damaged acoustical ceilings (1%=200sf).	۸,	1 200
Senior Center	group			\$	1,360
B037-Winchester	Ceiling	Ceiling group 1	Repair damaged areas of acoustical ceiling tiles as	_	
Street Garage	group	(acoustical tile)	required(30%=200sf).	\$	1,360
	Fire escape		Minor repair and scrape, paint steps (11R) at rear fire		
B002-Carr Building		Fire escape group 1			
	group		escape.	\$	1,397
B015 - Elliot St.	Canopy		6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Operations Center	group	Canopy group 1	Scrape, prepare surface and repaint wood trim (30sf).	\$	1,409
B003-Newton	Conduit		Replace junction box cover plates throughout interior and		
Senior Center	group	GRC Conduit	exterior of building (est. 3 int10 ext.)	\$	1,410
B031-Emmerson	Бгоар		exterior or building (est. 5 int. 10 ext.)	<u> </u>	
Community Center	Fan group	Fan group 1	Clean ventilation fan blades and lubricate fan bearings.	\$	1,422
B042-Upper Falls			Repair damaged areas of exterior concrete wall as required	7	1,722
1	Wall group	Wall group 1		\$	1,433
Fieldhouse			(10%=100sf).	٦	1,433
B035-Cabot Park	Flooring	Resilient VCT Flooring	Replace damaged areas of VCT flooring as required	ے ا	1 440
Fieldhouse			(30%=200sf).	\$	1,449
B040-Forte Park	Roofing		Install new drip edge along rear edge of roof (20lf) and		
(Allison)	group	Roofing group 1	repair asphalt shingles in the area which are damaged.	_	
	ысар		repair aspirate stilligies in the area willen are damaged.	\$	1,470
B035-Cabot Park	Door group	Bulkhead Door	Scrape, prepare surface and paint bulkhead door(1ea).		
Fieldhouse	Door group	Baikiicaa Booi	Scrape, prepare surrace and paint bankinead abortical.	\$	1,474
B029-Crafts Street	Bearing				
		Bearing wall group 1	Repair 20 LF of brick step cracking at the second floor.		
Garage	wall group			\$	1,478
D027 M/S- 1	Ext.				
B037-Winchester	lighting	Ext. lighting group 1	Add one exterior lighting unit to improve security.		
Street Garage	group	3 30 7 7 7	J 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$	1,552
	Ext.				•
B043-Highlands	lighting	Ext. lighting group 1	Add exterior wall pack to improve safety and security at		
Fieldhouse	group		dusk.	\$	1,552
B018-Waban	Canopy			<del>-</del>	_,55_
		Areaway Canopy	Seal underside of raw plywood (80sf) at areaway canopy.	\$	1,693
Library B036-Nahanton	group		Scrang caulk propare surface and renaint outgries soffit	۲	1,093
	Painting	Painting group 1	Scrape, caulk, prepare surface and repaint exterior soffit	۲	1 602
Park Fieldhouse	group	·	and trim (250lf).	\$	1,693
B022-Pelligrini Park	Accessibilit	Signage	Install tactile and Braille room and exit signage mounted	,	4 700
Field House	y Item	- 00-	adjacent to latch side door.	\$	1,700
B011 - Newton	Fan group	Ceiling Fans	Install exhaust fan in 2nd floor bathroom at 75 CFM per	١.	
Corner Library	I an group	Coming i diris	fixture.	\$	1,708

B041-Newton Ctr.					1	
Metal Storage	Door group	Door group 1	Repair and repaint overhead door (1ea).			
Building		200. 8. oap 1	(253)	\$	1,733	
B031-Emmerson	Other		Repair tripping hazard at transition from ramp to sidewalk			
Community Center	element	Exterior Ramps	(1ls).	١.		
community center	group		(113).	\$	1,735	
B006-Fire Station	Heating	Heating pumps group 5 -				
#1, Newton Corner	pumps	Domestic pump 1	Replace domestic heat pump.	\$	1,785	
B006-Fire Station	group	Fan group 4 - Kitchen		Ą	1,765	
#1, Newton Corner	Fan group	hood fan	Install new range fan.	\$	1,785	
	Heating			•	,	
B007-Fire Station	pumps	Heating pumps group 1 -	Replace heating condensate pump.			
#2, West Newton	group	condensate pump		\$	1,785	
B007-Fire Station	Heating	Heating pumps group 2 -				
#2, West Newton	pumps	oil pump	Replace heating oil pump.	,	4 705	
,	group			\$	1,785	
B010-Police Annex	Heating	Heating pumps group 3 -	Replace condensate pump with new condensate pump that			
BUTU-PUICE AITHEX	pumps group	condensate pump	has its own reservoir.	\$	1,785	
	Int			Υ	1,700	
B006-Fire Station	receptacles	Int receptacles group 1	Add more kitchen outlets to address blown fuses.			
#1, Newton Corner	group			\$	1,785	
B043-Highlands		Wall group 1	Repair damaged areas of exterior concrete walls as			
Fieldhouse	wan group	wan group 1	required (30 SF).	\$	1,800	
B042-Upper Falls	Int. Wall	Int. Wall		Repair areas of minor damage in exterior concrete and		
Fieldhouse	group	Int. Wall group 1	interior CMU walls as required and repaint(10%=140sf).	\$	1,832	
B034-Auburndale	Int. Wall			Ų	1,032	
Cove Fieldhouse	group	Int. Wall group 1	Clean, point, and paint interior CMU walls (20%=300sf).	\$	1,836	
B039-Bullough's	Element		Scrape and clean surface of wood trim and prepare surface	т		
Pond Shlter	group	Element group 1	for painting (250lf).	\$	1,847	
B028 - Jackson		Fan group 1 - bathroom	Replace bathroom fans with new, 75 CFM fans. Existing			
Homestead	Fan group	fans	controls can remain.			
Museum	147	14113	controls can remain	\$	1,930	
DO31 Countal Lake	Water	\\/atau  aatau /aliuaat\				
B021-Crystal Lake Bathhouse	heater (direct)	Water heater (direct) group 1	Install drip pan under unit and discharge to safe waste per code requirements.			
Battillouse	group	group 1	code requirements.	\$	1,965	
B024-Jeanette			Descript analysis stars	Ė	,	
Curtis West Rec Ctr	Element	Exterior Chimney Base	Repoint cracks in stone masonry base of exterior chimney			
(The Hut)	group		(100sf).	\$	1,990	
	Fuel		_			
B001-City Hall	Compresso	Compressor group 1	Remove non-functioning pneumatic compressor unit.	۲	2 000	
	r group		Build a weather-tight enclosure around the exterior	\$	2,000	
B038-Elliot Street	Service	Service entrance 1	mounted power service and panels to protect them against			
Sand_Salt Shed	entrance	Service entrance 1	the weather.	\$	2,018	
B032-Lower Falls	Int. Wall			-	,	
Community Center	group	Interior Drywall	Repair and repaint damaged areas of drywall (5%=400sf).	\$	2,022	
B036-Nahanton	Ductwork	Ductwork group 1	Clean ductwork thoroughly to remove all built up			
Park Fieldhouse	group	Dactwork Broah 1	particulates.	\$	2,104	

<u> </u>	ı	T			
	Water		Provide enclosure under the women's room sink to protect		
B036-Nahanton	heater	Water heater (direct) 2 -	water heater from tampering and from a child accidentally		
Park Fieldhouse	(direct)	Heater 2	hitting the pressure relief valve and getting scalded. Also		
	group		provide a drip pan and drain under the water heater.	,	2.404
202714//			provide a drip pair and aram ander the mater meater.	\$	2,104
B037-Winchester	Int. Wall	Int. wall group 2 (drywall)	Finish partially completed interior drywall partitions(500sf).	۲.	2 120
Street Garage	group	0 1 ( 7 7	1 , 1 , , ,	\$	2,138
B007-Fire Station	Ceiling	Plaster and Lathe Ceiling	Patch damaged sections of plaster and lathe ceiling (200sf).	_	2 4 2 2
#2, West Newton	group	0	σ, σ	\$	2,138
B010-Police Annex	Stair	Stair 1	Install 15If of missing railing on interior wood stairway.	\$	2,155
B036-Nahanton	Ceiling	Cailing analys 1	Replace damaged or stained acoustical ceiling tile		
Park Fieldhouse	group	Ceiling group 1	(20%=200sf).	\$	2,175
B028 - Jackson			Development of the second of t		
Homestead	Door group	Door Group 3 (other)	Rework lattice access door to operate for intended		
Museum		, ,	users(1ea 3/0x7/0). Clean area for accessibility.	\$	2,200
B035-Cabot Park			Clean and perform minor repairs on concrete flooring		
Fieldhouse	Flooring	Concrete Flooring	(260sf).	\$	2,224
	Water		(14000)		,
B015 - Elliot St.	heater	Water heater (direct)	Provide drain pan under unit with discharge piping to safe		
Operations Center	(direct)	group 1 - kitchen hw htr	waste per code requirements.		
Operations center	1	group 1 - kitchen nw nti	waste per code requirements.	\$	2,233
B015 - Elliot St.	group			7	2,233
	Door group	Doors	Replace weather stripping at pairs of loft doors (2ea).	\$	2,233
Operations Center B022-Pelligrini Park				٧	2,233
_	Fan group	Fan group 2 - kitchen fan	Replace kitchen exhaust fan with a new fan unit.	۲	2 420
Field House		5		\$	2,430
B022-Pelligrini Park	Fan group	Fan group 3 - TV room	Replace TV room exhaust fan with a new fan unit.	۲.	2 420
Field House		fan	D : 1	\$	2,430
B019 - Nonantum	Fan group	Fan group 2 - basement	Provide new exhaust fan, 75 CFM in basement womens	,	2 420
Library		womens room	room. Interlock controls with light.	\$	2,430
B030-Elliot Street	Fan group	Fan Group 2 - Garage	Replace garage office fan with a code-compliant fan with	_	2 420
Yard Garage	8 p	Office Fan	protected blades.	\$	2,430
B028 - Jackson					
Homestead	Door group	Door Group 4 (bulkhead)	Repair basement wood bulkhead door(1ea).	١.	
Museum				\$	2,433
B013 - Kennard	Heating				
Estate	pumps	Heating pumps group 1	Reconnect heat pump and provide controls.		
Estate	group			\$	2,433
B018-Waban	Egress	Faross Lighting 1	Add egress lighting fixtures (2) units to toilets.		
Library	Lighting	Egress Lighting 1	Add egress lighting fixtures (2) units to tollets.	\$	2,465
	Column		Clean and repaint corroded areas at bases of two steel		
DOOA City Hall		Column Group Summary	comumns in lower basement (boiler room) that are heavily		
B001-City Hall	Group	1	corroded. After cleaning, inspect for loss of section and		
	Summary		repair if necessary.	\$	2,481
B027-Public	Ext				
Buildings		Ext receptacles group 1	Install (4) all-weather GFI receptacles along the perimeter		
Department	group		of the structure.	\$	2,487
	Ext			Т.	,
B017- Newton Free		Exterior Receptacles	Install (~4) all-weather GFI receptacles at or near exterior		
Library	-	Exterior neceptacies	doorways.	\$	2,487
B008-Newton	group			7	_,,
Police	Flooring	Flooring group 1	Repair concrete floor as required(20%=400sf)		
	i looring	(concrete)	mepan concrete noor as requireu(20%-400si)	\$	2,487
Headquarters	ļ			٧	40/

B024-Jeanette	Ext				
Curtis West Rec Ctr	-	Ext receptacles group 1	Add (4) Exterior GFI Receptacle front and rear entrance.		
(The Hut)	group			\$	2,487
B026-Burr Park	Ext		Add (4) Exterior CEL Becontacted at the front and rear		
	receptacles	Ext receptacles group 1	Add (4) Exterior GFI Receptacles at the front and rear		
Field House	group		entrances.	\$	2,487
	CW		Provide combustion air dampers at openings, or provide		
B036-Nahanton	service/me	CW service/meter group	heat trace on cold water service piping. Note there is a wall		
Park Fieldhouse	ter group	1	switch for heat trace, but no heat trace line present.	ـ ا	2 505
	ter group		switch for heat trace, but no heat trace line present.	\$	2,505
B024-Jeanette	Bearing				
Curtis West Rec Ctr	wall group	Bearing wall group 1	Pack 5 SF of gaps in brick with non-shrink grout.	ے ا	2 527
(The Hut)				\$	2,527
B036-Nahanton	Other	5 . 5 .			
Park Fieldhouse	element	Entry Pad	Repair crack in concrete entry pad at door threshold (30sf).	ے	2 566
	group		Denois democrat associate floor slab as servined	\$	2,566
B043-Highlands Fieldhouse	Flooring	Flooring 1	Repair damaged areas of concrete floor slab as required	\$	2,581
B005-Crafts St DPW			(250 SF).	٦	2,361
Operating Ctr	Painting	Painting group 1	Scrape, prepare surface and repaint (350lf).		
(Stable)	group	(woodwork)	Scrape, prepare surface and repaint (55011).	\$	2,586
B041-Newton Ctr.				7	2,300
Metal Storage	Wall group	Wall group 2	Repair damaged areas of concrete foundation wall (400sf).		
Building	Wan group	Wall Broap 2	repair duringed dreas of concrete roundation wait (40051).	\$	2,586
B011 - Newton				<u> </u>	_,-,
Corner Library	Sink group	Sinks	Replace 2nd floor sink.	\$	2,638
B022-Pelligrini Park	G: 1	Sink Group 2 - Janitor's			,
Field House	Sink group	Sink	Replace janitor's sink.	\$	2,638
B008-Newton	Int. Door	Interior deer group 2			
Police		Interior door group 2	Repair pair of doors as required(20% =1ea)		
Headquarters	group	(double hung)		\$	2,638
B032-Lower Falls	Millwork	Wood Cubbies	Repair wood cubby's in corridor (1ls).		
Community Center	group	Wood Cubbles	nepair wood cabby 3 iii corridor (113).	\$	2,638
B009-Police	Specialties				
Headquarters	group	Bathroom Accessories	Install new bath accessories in bathrooms (2ea).		
Garage				\$	2,640
	Sanitary				
B035-Cabot Park	sump	Sanitary sump pump	Replace sump pump because it is at the end of its useful		
Fieldhouse	pump	group 1	life (1ea).	ے	2 662
DOZO A ula uma da la	group	Can avanua 1 1 t flagg		\$	2,663
B020-Auburndale	Fan group	Fan group 1 - 1st floor	Install 75 CFM fan to exhaust air per code requirements.	\$	2,663
Library B009-Police		janitor closet		۲	2,003
Headquarters	Accessibilit	Exterior	Re-surface the accessible walkway so that the surface is		
Garage	y Item	LACCIO	stable, firm and slip resistant.	\$	2,700
B009-Police	<del> </del>			۲	_,, 55
Headquarters	Ceiling	Acoustical Tile Ceiling	Repair or replace acoustical ceilings (50%=400sf).		
Garage	group			\$	2,719
	Sanitary				-
B013 - Kennard	sump	Charma Bin i	Danie a francis analysis is a second		
Estate	pump	Storm Piping	Replace/repair cracked storm drainage piping.		
	group			\$	2,719
B035-Cabot Park	Ceiling	Concrete Ceiling	Repair damaged areas of concrete ceiling (40%=100sf).		
Fieldhouse	group	Somerete Senning	nepall adminged areas of concrete telling (40/0-10031).	\$	2,733

B021-Crystal Lake	Roof deck		Repair 25 SF of concrete slab in room where the slab has		
Bathhouse	group	Roof deck group 1	deteriorated.	\$	2,750
	Radiation/t	Dadiatia a /tanasia al ancora			ĺ
B003-Newton Senior Center	erminal	Radiation/terminal group 3 - Unit ventilators	Replace filters and clean coils at unit ventilators.		
	unit group	3 - Unit Ventuators		\$	2,825
B035-Cabot Park	Lintels	Lintels group 1	Repair deteriorated lintels at exterior brick masonry walls		
Fieldhouse	group	Intelligioup I	as required (50lf).	\$	2,849
B042-Upper Falls	Ceiling	Ceiling group 1	Scrape, repair, prepare surface and repaint concrete ceiling	\$	2 902
Fieldhouse	group Radiation/t		(500sf)	Ş	2,892
B029-Crafts Street	erminal	Radiation/terminal 2 -	Replace electric baseboard sections in office area with new		
Garage	unit group	office electric baseboard	baseboard units.	\$	2,895
B005-Crafts St DPW	unit group			<u> </u>	,
Operating Ctr	Flooring	Flooring group 2 (VCT)	Repair VCT floor as required (10%=400sf).		
(Stable)				\$	2,898
B035-Cabot Park	Ceiling	Acoustical Tile Ceiling	Remove damaged acoustical tiles and replace with new tile		
Fieldhouse	group	Acoustical file Celling	(50%=300sf).	\$	2,914
	Sanitary				
B029-Crafts Street	sump	Sanitary sump pump	Replace sump pump.		
Garage	pump	group 1	Special Property of the Control of t	ے ا	2 020
	group		Replace electrical PVC conduits and enclosed wiring at	\$	2,930
B038-Elliot Street	Conduit	Conduit group 1	exterior panelboards where found to be cracked or joints		
Sand_Salt Shed	group	Conduit group 1	separated.	\$	2,952
B033-Albermarle	Egress		Replace battery back-up packs in egress lights (2 ea) which		2,332
Fieldhouse	Lighting	Egress Lighting	failed when tested.	\$	3,103
			Replace existing exterior lighting fixtures with 2 new		,
B042-Upper Falls	Ext.	Fut lighting group 1	outdoor LED fixtures on the entrance patio to improve		
Fieldhouse	lighting	Ext. lighting group 1	lighting levels, reduce maintenance and improve energy		
	group		efficiency.	\$	3,103
B003-Newton	Ext		Install all-weather GFI receptacles at or near exterior		
Senior Center	· ·	Ext receptacles group 1	doorways (5 ea).	ـ ا	2.400
	group Ext		, , ,	\$	3,109
B010-Police Annex		Ext receptacles group 1	Add 5 all-weather GFI receptacles along the perimeter of		
BU10-PUICE ATTIEX		Extreceptacies group 1	the structure.	\$	3,109
	Ext			7	3,103
B011 - Newton	_	Ext receptacles group 1	Add 5 all-weather GFI receptacles along the perimeter of		
Corner Library	group		the structure.	\$	3,109
B005-Crafts St DPW	Ext		Install 5 all-weather GFI receptacles along the perimeter of		
Operating Ctr	receptacles	Ext receptacles group 1	the structure.	١.	
(Stable)	group		the structure.	\$	3,109
B022-Pelligrini Park	Ext	_			
Field House	-	Exterior Receptacles	Install exterior GFI sockets at exterior doors (Est. 5).	لم ا	2 100
B028 - Jackson	group Ext			\$	3,109
Homestead		Ext receptacles group 1	Add 5 all-weather GFI receptacles along the perimeter of		
Museum	group	Lyr receptacies group 1	the structure.	\$	3,109
	Ext			Ť	3,203
B032-Lower Falls	_	Ext receptacles group 1	Add 5 all-weather GFI receptacles along the perimeter of		
Community Center	group	0.00	the structure.	\$	3,109
B026-Burr Park		Stair 1	Install new code-compliant hand railings to basement		
Field House	Stair	Stair 1	(35lf).	\$	3,130
B018-Waban	Fan group	Fan group 1 - Basement	Provide cover for basement transfer fan to protect fan	_	
Library	B. oup	transfer fan	blades.	\$	3,163

	<u> </u>		Dravida 75 CEM ashaust fan and dustwark far hasament		
B018-Waban	Fa	Fan group 2 - Basement	Provide 75 CFM exhaust fan and ductwork for basement bathroom and vent to outside. Interlock fan with light		
Library	Fan group	bathroom 1	_	\$	3,163
DO10 Wohan		Fan group 4 1st floor	switch.	Ą	3,103
B018-Waban	Fan group	Fan group 4 - 1st floor	Provide 75 CFM exhaust fan and ductwork and vent to	\$	2 162
Library		bathroom	outside for first floor bathroom.	Ą	3,163
B018-Waban	Fan group	Fan group 5 - Janitors	Provide 75 CFM exhaust fan and ductwork and vent to	\$	2 162
Library	Cooling	closet	outside.	Ą	3,163
B001-City Hall	piping/insu lation group	Cooling piping/insulation group 1	Replace and reinsulate outdoor exposed sections of cooling piping.	\$	3,163
B019 - Nonantum Library	Flooring	Resilient VCT	Replace VCT floor (400sf).	\$	3,200
B037-Winchester Street Garage	Painting group	Painting group 1 (woodwork)	Prepare surface and paint(180lf).	\$	3,221
B042-Upper Falls	Int. Door		Repair minor damage on interior hollow metal doors and		,
Fieldhouse	group	Int. Door group 1	repaint (3ea).	\$	3,263
B027-Public					-
Buildings	Int. Door	Int. Door group 1	Replace door from office to garage with fire rated door and		
Department	group	2	frame (1ea).	\$	3,360
B037-Winchester	<u> </u>	Door group 1 (single	Replace front entry door with new door and hardware	•	
Street Garage	Door group	hung)	(1ea).	\$	3,360
B009-Police			(1-5%).		,
Headquarters	Fan group	Fan Group 2 - Ceiling	Replace fan in garage that is not working (1ea).		
Garage		Fans		\$	3,363
	Accessibilit		Install tactile and Braille room and exit signage adjacent to		-,
B012-Gath Pool	y Item	Signage	latch side of doors.	\$	3,400
B008-Newton	,		14401101400101	·	,
Police	Generator	Generator 1	Replace leaking radiator for emergency generator.		
Headquarters				\$	3,417
					,
B033-Albermarle	Foundation	Foundation wall group 1	Fix large crack on the outside of the perimeter foundation		
Fieldhouse	wall group	0	wall at the NW corner of building.	\$	3,417
B036-Nahanton	Element				,
Park Fieldhouse	group	Cupola	Repair minor damage on cupola and refinish (1ea).	\$	3,465
B037-Winchester	Ceiling		Repair damaged areas of plaster ceiling as required	-	
Street Garage	group	Ceiling group 2 (plaster)	(50%=600sf).	\$	3,471
B043-Highlands	Int. Wall		Repair damaged areas of interior CMU wall as required (80	-	
Fieldhouse	group	Int. Wall group 1	SF).	\$	3,572
B002-Carr Building	Accessibilit y Item	Parking	Restripe the accessible parking space to have a 96" wide access aisle. Install a sign indicating "van accessible" parking; Re-grade and re-surface accessible parking and access to it so that slopes do not exceed 2%; Re-stripe rear accessible parking to include an access aisle @96" wide and parking @ 96" wide. Provide signage that includes "van" accessible.	\$	3,583
B011 - Newton Corner Library	Accessibilit y Item	Toilet Rooms	Insulate the pipes in the accessible toilet room to protect against contact; Reposition the mirror or install a full length mirror; Replace the faucets with lever type hardware; Install a new flush valve so that it is on the wide side of the toilet; Bevel threshold at accessible toilet room both sides so that slope is no greater than 1:2.	\$	3,600

DOOG Time Chatian	1	<u> </u>	<del> </del>	
B006-Fire Station #1, Newton Corner	Flooring	Resilient VCT Flooring	Repair damaged areas of VCT floor (10%=400sf).	\$ 3,639
B035-Cabot Park Fieldhouse	Roofing group	Hip Roof	Repair/replace gutters and downspouts at hip roof area(60lf).	\$ 3,724
B006-Fire Station #1, Newton Corner	Ext. lighting group	Ext. lighting group 1	Replace all exterior lighting (6 wall pack units) to improve safety & security and provide a lighting controller system.	\$ 3,730
B026-Burr Park Field House	Egress Lighting	Egress Lighting	Add (6) egress lighting and lit EXIT signs at exits.	\$ 3,730
B028 - Jackson Homestead Museum	Roofing group	Roofing group 1 (gable)	Add historically appropriate gutter and downspouts to rear of shed roof (70lf).	\$ 3,807
B029-Crafts Street Garage	Int. Door group	Int. door group 2 (double hung typical)	Repair, prepare surfaces and paint /seal double hollow metal and wood interior doors (4ea).	\$ 3,912
B036-Nahanton Park Fieldhouse	Ext. lighting group	Ext. lighting group 1	Replace all exterior lighting to improve safety and security and include a lighting controller system to improve energy efficiency.	\$ 3,958
B035-Cabot Park Fieldhouse	Ext. lighting group	Ext. lighting group 1	Replace all exterior lighting to improve safety and security and include a lighting controller system to improve energy efficiency.	\$ 3,958
B013 - Kennard Estate	Ext. lighting group	Ext. lighting group 1	Upgrade exterior lighting with energy efficient fixtures with a lighting controller.	\$ 4,034
B010-Police Annex	Ceiling group	Acoustical Tile Ceiling	Replace broken stained acoustical ceiling (20%=600sf).	\$ 4,079
B002-Carr Building	Door group	Ext. Double Hung Doors	Replace weather stripping at center mullion of double hung doors (11ea).	\$ 4,133
B019 - Nonantum Library	Door group	Double Hung Exterior Doors	Repair, refinish pair of wood doors as required (1ea).	\$ 4,163
B009-Police Headquarters Garage	Roof deck group	Roof deck group 1	Repair cracking of the roof slab and the hole in the roof slab in the evidence area.	\$ 4,276
B003-Newton Senior Center	Painting group	Painting group 1	Scrape, prepare surface of wood work for painting (50%=1000sf).	\$ 4,276
B019 - Nonantum Library	Accessibilit y Item	Signage	Install tactile and Braille room and exit signage adjacent to latch side of door at all permanent rooms and space; Provide directional signage to the accessible entrance at the main entrance; Provide directional signage to the accessible toilet room.	\$ 4,300
B011 - Newton Corner Library	Wall group	Wall group 1	Renail and repair exterior wood clapboard siding 5% (230sf). Remove plywood enclosure strip(20sf) and replace with durable enclosure wall.	\$ 4,303
B043-Highlands Fieldhouse	Dom. water piping/insu lation group	Dom. water piping insulation 1 - water fountain	Reroute piping for drinking fountain with hard piping that is firmly secured to wall.	\$ 4,304
B020-Auburndale Library	Lintels group	Lintels group 1	Scrape, prepare surface and repaint exposed areas of steel lintels(50lf).	\$ 4,349
B029-Crafts Street Garage	Air handler group	Air handler group 1	Provide filters for MU-1, MU-2, and make up air unit. Replace piping for condensate drain and comb condenser fins at RTU-1.	\$ 4,351
B013 - Kennard Estate	Ext receptacles group	Ext receptacles group 1	Install all-weather GFI receptacles along the perimeter of the structure (7ea).	\$ 4,352

B013 - Kennard	Ceiling	Ceiling group 1	Repair 10% of plaster and lath ceilings (350sf). Repair 40%	
Estate	group	668 8. oak 1	of basement plaster and lath ceiling(360sf).	\$ 4,414
B031-Emmerson	Door group	Door group 1	Refurbish single hollow metal doors (3ea minor) and pairs	
Community Center		Door group 1	of hollow metal doors (3ea minor) as required.	\$ 4,428
B035-Cabot Park Fieldhouse	Heating piping/insu lation group Dom.	Heating piping/insulation  1 - hot water piping	Insulate all exposed heating piping that is not insulated.	\$ 4,509
B035-Cabot Park Fieldhouse	water piping/insu lation group	Dom. water piping/insulation group 1	Install insulation on all exposed hot water piping.	\$ 4,509
B033-Albermarle Fieldhouse	Slab on grade group	Slab on grade group 1	Remove all existing exterior concrete slab coatings, seal cracks in slab, and reseal with a concrete sealer.	\$ 4,509
B024-Jeanette Curtis West Rec Ctr (The Hut)	Ceiling group	Plaster and Lathe	Patch, repair, paint plaster ceiling in basement (500sf).	\$ 4,581
B011 - Newton Corner Library	Accessibilit y Item	Signage	Install tactile and Braille signage adjacent to latch side of door at all permanent rooms and space and at exits; Provide signage to accessible bathroom; relocate kitchen to accessible level unless an elevator is installed to second floor.	\$ 4,600
B031-Emmerson Community Center	Ceiling group	Plaster and Lathe Ceilings	Repair plaster ceiling (50% =1000sf).	\$ 4,622
B027-Public Buildings Department	Flooring	VCT Flooring	Remove and replace VCT flooring (500sf).	\$ 4,857
B019 - Nonantum Library	Egress Lighting	Egress Lighting 1	Add egress lighting fixtures (2) units to toilets.	\$ 4,860
B003-Newton Senior Center	Flooring	Carpet Flooring	Replace interior carpet (500sf).	\$ 4,903
B016-Crafts Street Sand_Salt Shed	Ext receptacles group	Ext receptacles group 1	Install two all-weather GFI exterior power receptacles at each hut (4 total).	\$ 4,930
B018-Waban Library	Ext receptacles group	Ext receptacles group 1	Add (4) exterior all-weather GFI receptacles around the perimeter of the building.	\$ 4,930
B020-Auburndale Library	group	Ext receptacles group 1	Add (4) exterior all-weather electrical GFI receptacles.	\$ 4,930
B035-Cabot Park Fieldhouse	Roofing group	Flat Roof	Repair flashing and downspouts at flat roof area (80lf).	\$ 4,965
B028 - Jackson Homestead Museum	Int. Door group	Int. Door group 2	Refit, minor repair pairs of 6 panel double doors as required (4ea).	\$ 4,974
B027-Public Buildings Department	Wall group	CMU Exterior Walls	Clean and repaint exterior CMU wall (40%=800sf).	\$ 4,974
B018-Waban Library	Int. Wall group	Concrete Walls	Clean mold and seal with water lock paint located at basement floor to wall line(100lf).	\$ 5,000
B029-Crafts Street Garage	Window group	Window group 2 (store front)	Install and/or repair storefront rubber glazing seals(140sf).	\$ 5,010

DOSS Alberterals	1	Cink group 1   lanitari	Г	1	1
B033-Albermarle Fieldhouse	Sink group	Sink group 1 - Janitor's Sink	Replace/fix janitor's sink.	\$	5,044
B008-Newton Police Headquarters	Int. Door group	Interior door group 1 (single hung)	Repair single hung doors (10% =3ea)	\$	5,125
B001-City Hall	Wall group	Exterior Brick Masonry Walls	Repair vertical crack full height at rear left corner (25lf). Infill all misc. opening in masonry wall(1ls).	\$	5,257
B026-Burr Park Field House	Fan group	Fan group 1	Provide exhaust fans at 75 CFM per toilet/urinal. Interlock fans with light switches to bathrooms.	\$	5,277
B030-Elliot Street Yard Garage	Ext. lighting group	Ext. lighting group 1	Add (4) exterior lighting units with a lighting controller system to corners of building to improve security.	\$	5,277
B020-Auburndale Library	Egress Lighting	Egress Lighting 1	Add egress lighting fixtures (2) units to toilets and replace battery back-ups in all Egress lighting.	\$	5,325
B036-Nahanton Park Fieldhouse	Sink group	Water Fountain at Entry	Replace missing water fountain near entry.	\$	5,428
B018-Waban Library	Sanitary sump pump group	Drainage Piping	Repair leaking drain pipe in Janitors closet.	\$	5,544
B031-Emmerson Community Center B039-Bullough's	Int. Wall group Painting	Plaster and Lathe Walls	Repair damaged areas of plaster wall as required (30%=1200sf).  After clapboard siding repair, scrape, prepare surface for	\$	5,547
Pond Shiter	group	Painting group 1	painting, and repaint clapboard siding (1300sf).	\$	5,559
B001-City Hall	Hydronic accessories group	Hydronic accessories group 1	Replace steam traps.	\$	5,583
B018-Waban Library	Fire/Smoke Alarm System	Fire/Smoke Alarm System 1	Install audible alarms in toilets for fire alarm system to meet ADA requirements (4ea).	\$	5,860
B010-Police Annex	Flooring	Carpet Flooring	Replace Carpet Flooring(30%=600sf).	\$	5,883
B034-Auburndale Cove Fieldhouse	Painting group	Painting group 1	Clean entire surface(1400sf). Paint areas that needs touch up (10%=140sf).	\$	5,987
B028 - Jackson Homestead Museum	Int. Wall group	Int. Wall group 1 (typical interior walls)	Scrape, repair, paint plaster walls(30% =1400sf).	\$	5,987
B028 - Jackson Homestead Museum	Conduit group	Conduit group 1	Tie back flexible conduit to meet electrical code.	\$	5,987
B027-Public Buildings Department	Stair	Stair 1	Remove carpet at wood stairs between office and garage and replace with rubber treads (3r).	\$	6,056
B001-City Hall	Slab on grade group	Slab on grade group 1	Removed standing water on basement floor.	\$	6,141
B033-Albermarle Fieldhouse	Ext. lighting group	Ext. lighting group 1	Install additional exterior lighting (4 wall pack units) to improve safety & security with a lighting contoller system to improve energy efficiency.	\$	6,207
B009-Police Headquarters Garage	Ext. lighting group	Ext. lighting group 1	Replace existing exterior lighting fixtures and add four more to improve on light levels in the courtyard.	\$	6,217
B011 - Newton Corner Library	Int	Int receptacles group 1	Add additional duplex receptacle to each office location (~10 locations) to address extensive use of power strips.	\$	6,217

	T	T	1	
B013 - Kennard Estate	group	Int receptacles group 1	Add additional electrical duplex receptacles (~10 locations).	\$ 6,217
B029-Crafts Street Garage	Ext receptacles group	Ext receptacles group 1	Install (10) all-weather GFI receptacles at or near exterior doorways.	\$ 6,217
B030-Elliot Street Yard Garage	Ext receptacles group	Ext receptacles group 1	Add 1 duplex receptacle per exterior door. (est. 10 receptacles)	\$ 6,217
B031-Emmerson Community Center	Int. Wall group	Brick Masonry Walls	Repair damaged areas of interior brick masonry wall as required (5%=900sf).	\$ 6,344
B039-Bullough's Pond Shlter	Wall group	Wall group 1	Repair siding where damaged or loose. Scrape and clean siding surface (1300sf).	\$ 6,396
B022-Pelligrini Park Field House	Lintels group	Lintels	Clean and repaint lintels at exterior doors(4ea).	\$ 6,465
B008-Newton Police Headquarters	Door group	Door group 1 (single hung)	Repair exterior doors as required(2ea)	\$ 6,672
B019 - Nonantum Library	Int. Wall group	Plaster and Lath Walls	Patch, scrape, prepare surfaces and paint areas of damaged coating/paint on walls (40%=600sf).	\$ 6,698
B022-Pelligrini Park Field House	Ceiling group	Plaster and Lathe	Repair plaster and lath ceiling in boiler room (300sf).	\$ 6,698
B026-Burr Park Field House	Flooring	Resilient VCT Flooring	Remove mismatched VCT tiles and patch with similar tiles (40% =900sf).	\$ 6,763
B024-Jeanette Curtis West Rec Ctr (The Hut)	Fire/Smoke Alarm System	Fire/Smoke ALarm	Upgrade Fire/Smoke detectors with audible alarms and strobes to meet ADA requirements	\$ 6,789
B032-Lower Falls Community Center	Ceiling group	Acoustical Ceiling Tile	Remove and replace damaged acoustical ceiling tiles (10% = 700sf).	\$ 6,800
B019 - Nonantum Library	Ext receptacles group	Ext receptacles group 1	Install (4) all-weather GFI receptacles around the exterior of the building.	\$ 6,930
B018-Waban Library	Toilet/urin al group	Toilet/urinal group 1	Replace toilet in basement bathroom which has backed up sewage waste. This is an immediate health hazard.	\$ 6,961
B018-Waban Library	Ceiling group	Plaster and Lathe	Repair water damaged areas of plaster ceiling and paint(10% =500sf).	\$ 7,000
B039-Bullough's Pond Shlter	Foundation wall group	Pier Foundations	Install galvanized steel ties between the wood structure framing and the concrete piers under the building to properly secure the building. In areas where the wood framing does not have sufficient bearing area on the piers, provide additional sistering of joists with shims to increase the bearing area.	\$ 7,004
B024-Jeanette Curtis West Rec Ctr (The Hut)	Flooring	Resilient VCT	Repair/replace VCT basement floor (50% =700sf).	\$ 7,076
B027-Public Buildings Department	Roofing group	Flat Roof	Repair and re-flash skylights as required (7ea).	\$ 7,076
B001-City Hall	Stair group (structure)	Stairs	Clean and paint steel egress stairs from Boiler Room to exterior and secure loose grating steps. After steel clean, inspect steel framing for loss of section and repair if necessary.	\$ 7,117

B018-Waban Library	Element group	Window Grates	Remove areaway grates, clean out areaways, paint grates and reinstall grates (100sf).	\$ 7,163
B029-Crafts Street	Stair	Stair group 2	Add handrail to interior metal stair on the wall side(50lf)	\$ 7,182
Garage B019 - Nonantum Library	Door group	Single Hung Exterior Doors	Repair single hung wood doors as required and replace thresholds, door hardware(2ea).	\$ 7,185
B007-Fire Station #2, West Newton	Accessibilit y Item	Parking	Restripe designated parking space to have an 8 ft. access aisle; Install a new parking sign with the words "Van Accessible"; Install a curb ramp to provide accessible path from designated accessible space to entrance.	\$ 7,250
B017- Newton Free Library	Other element group	Exterior ramp	Repoint open joints in brick pavers of ramp (100 sf). Remove and reset heaving bricks at railing posts (50 sf). Touch-up paint metal railings.	\$ 7,290
B010-Police Annex	Door group	Single Hung Doors	Repair (minor) single hung doors and hardware (3ea).	\$ 7,299
B035-Cabot Park Fieldhouse	Painting group	Painting group 1	Paint Exterior masonry wall (1500sf). Scrape, prepare surface and paint exterior wood trim work (200sf).	\$ 7,339
B029-Crafts Street Garage	Roof beam group	Roof beam group 3	Repaint steel in wash bay	\$ 7,390
B037-Winchester Street Garage	CW service/me ter group	CW service/meter group 1	Provide a heated enclosure for above ground exposed portions of cold water service on the outside of the building so that water service does not have to be drained in the winter.	\$ 7,440
Elliot street Sand and Salt Shed			Remove salt stock pile. Repair, clean and seal concrete floor (7500sf) to increase the useable life of the floor.	\$ 10,197
B001-City Hall	Door group	Single Hung Exterior Doors	Repair, scrape, prepare surface and paint exterior single hung doors and add ADA panic hardware, weather stripping (3ea).	\$ 7,443
B006-Fire Station #1, Newton Corner	Ceiling group	Acoustical Tile Ceiling	Repair 12x12 acoustical ceiling(20%=700sf)	\$ 7,483
B037-Winchester Street Garage	Communic ation room	Communication room 1	Build out a dedicated secured 8'x'10 TR area to prevent accidental damage of Telecom components.	\$ 7,614
B024-Jeanette Curtis West Rec Ctr (The Hut)	Other element group	Side Entry Steps	Rebuild wood stairs at left and install new handrails(30lf). Repair /replace plywood stair enclosure (200sf).	\$ 7,764
B037-Winchester Street Garage	Element group	Element group 2 (fascia trim)	Replace wood fascia, soffit and rake trim(180lf).	\$ 7,843
B001-City Hall	Ext. lighting group	Exterior Lighting	Convert exterior lighting to LED to reduce frequency of maintenance and improve efficiencies.	\$ 7,908
B037-Winchester Street Garage	Int. Door group	Int. door group 1 (single hung)	Repair/ replace wood interior doors(3ea).	\$ 7,915
B027-Public Buildings Department	Egress Lighting	Egress Lighting 1	Add (6) egress and EXIT signs per code to office and garage bay.	\$ 7,915
B018-Waban Library	Condensin g units group	Condensing units group 2	Provide condensate pump for humidifier unit. Provide new flexible piping for drain and route to outside.	\$ 7,958
B010-Police Annex	Flooring	Resilient VCT Flooring	Replace VCT Flooring(40%=1100sf).	\$ 7,969

B031-Emmerson	Lintels	Lintels group 1	Repair/reset lintels in areas with bulging brick as required	
Community Center	group	Linters group 1	(20%=60lf).	\$ 8,170
B029-Crafts Street Garage	Water heater (direct) group	Water heater (direct) group 1	Replace garage sink hot water heater with new electric hot water heater. Install drip pan under office hot water unit and discharge piping to safe waste per code requirements.	\$ 8,171
B001-City Hall	Roof deck group	Oil Tank Roof	Seal open hole from missing oil tank fill cover in concrete slab above abandonned oil tank. Patch roadway pavement. Drain standing water from oil tank containment area.	\$ 8,325
B020-Auburndale Library	Fire/Smoke Alarm System	Fire/Smoke Alarm System 1	Install audible alarms in toilets for the fire alarm system to meet ADA requirements.	\$ 8,330
B010-Police Annex	Sanitary sump pump group	Storm Drainage	Replace section of pipe that is missing. Clean blockages from both storm drain pipes.	\$ 8,410
B013 - Kennard Estate	Roof beam group	Roof beam group 1	Install collar ties at roof rafters- low attic under.(150sf)	\$ 8,546
B019 - Nonantum Library	Ext. lighting group	Ext. lighting group 1	Replace all exterior lighting (6 wall pack units) to improve safety & security and include lighting controller system.	\$ 8,580
B007-Fire Station #2, West Newton	Door group	Single Hung Doors	Replace exterior single hung doors with panic hardware (3ea).	\$ 8,613
B015 - Elliot St. Operations Center	Ext. lighting group	Ext. lighting group 1	Add four more wall pack lights to exterior of building to improve lighting conditions at night.	\$ 8,650
B015 - Elliot St. Operations Center	Accessibilit y Item	General Interior	Provide an accessible bench, locker and table in the central locker area; Replace faucets in the kitchenette to be ADA-compliant; Reposition or remove television in kitchenette; Replace door knobs with hardware that is operable without tight grasping, pinching or twisting (lever type).	\$ 8,700
B027-Public Buildings Department	Ceiling group	Ceiling group 1	Scrape, prepare suface and repaint office ceiling (2100sf).	\$ 8,741
B031-Emmerson Community Center	Int receptacles group	Int receptacles group 1	Add additional GFI receptacles to classroom space.	\$ 8,980
B031-Emmerson Community Center	Ext receptacles group	Ext receptacles group 1	Add GFI receptacles to exterior of building near each entrance.	\$ 8,980
B013 - Kennard Estate	Egress Lighting	Egress Lighting	Install code-compliant egress signage and lighting.	\$ 9,022
B008-Newton Police Headquarters	Ceiling group	Ceiling group 1 (acoustical tile)	Replace/repair stained or broken acoustical ceiling as required (10%=1300sf).	\$ 9,031
B012-Gath Pool	Ext. lighting group	Ext. lighting group 1	Replace exterior lighting around building to improve security.	\$ 9,052
B001-City Hall	Element group	Soffits	Remove out bird nests from front and rear soffits, prepare wood surfaces and repaint (400sf).	\$ 9,120

	Ext.	Ī	Replace lighting existing fixtures (6 Units) and add two		
B010-Police Annex		Fut lighting group 1	l · · · · · · · · · · · · · · · · · · ·		
BU10-Police Annex	lighting	Ext. lighting group 1	more to parking area to improve on light levels in the	\$	9,310
	group Ext.		parking lot.  Replace all exterior lighting lighting units to improve safety,	γ	9,310
B034-Auburndale	_	Fut liabtica avanua 1	1		
Cove Fieldhouse	lighting	Ext. lighting group 1	security and energy efficiency. Install a lighting control	\$	9,310
B024-Jeanette	group Ext.		system to improve energy efficiency.	۲	3,310
Curtis West Rec Ctr	lighting	Ext. lighting group 1	Add exterior lighting wall pack units (10ea) to improve		
	-	Ext. lighting group 1	safety & security.	\$	9,825
(The Hut) B018-Waban	group Int. Wall		Repair water damaged and paint peeling areas of plaster	7	3,023
		Plaster and Lathe Walls	walls (15%=900sf).	\$	9,900
Library	group Other		Install two new rubber bumpers at loading dock. Patch	7	3,300
B017- Newton Free		Exterior leading dock	·		
Library	element	Exterior loading dock	spalled concrete at loading dock knee wall and clean & coat	\$	9,902
B034-Auburndale	group		exposed rebar (150 sf). Replace exterior FRP doors that have corroded metal	7	3,302
Cove Fieldhouse	Door group	Exterior Doors	frames with new (3ea).	\$	10,080
B043-Highlands			Iranies with new (sea).	7	10,000
Fieldhouse	Door group	Door group 1	Install new exterior doors and hardware(3ea).	¢	10,080
B032-Lower Falls	Conduit		Tie back loose and unsecured flexible electrical conduit to	7	10,000
		Conduit group 1	meet electrical code.	ς	10,615
Community Center	group Sanitary		inteet electrical code.	7	10,013
B007-Fire Station	sump		Replace internal storm drain piping which is blocked and		
		Storm Drainage Piping	leaking causing ice dams.		
#2, West Newton	pump		leaking causing ice dams.	\$	10,641
B039-Bullough's	group			7	10,041
Pond Shiter	Door group	Door group 1	Replace all exterior doors, frames, and hardware (3ea).	ς	10,778
Foria Sinter			Replace missing indoor drinking fountain and non-	Υ	10,770
B034-Auburndale	Sink group	Drinking Fountains	functioning outdoor drinking fountain with new ADA-		
Cove Fieldhouse	January State	2	compliant fountains.	\$	10,856
B034-Auburndale	Int. Door	Int. Dear man 1			
Cove Fieldhouse	group	Int. Door group 1	Remove and replace doors and hardware(5ea).	\$	10,867
B027-Public	Lighting	Lighting controllers group	Add occupancy sensors to the office area and garage to		
Buildings	controllers	11	improve energy efficiency.		
Department	group	1	improve energy emciency.	\$	10,971
B028 - Jackson	Other		Replace all rotted treads and decking at rear wood deck as		
Homestead	element	Other element group 6	required(200sf). Install historical gutters and		
Museum	group	(rear wood stair)	downspouts(70lf). Clean off moss from stair entry pad.		
	group		downspouts(7011). Clean on moss from stall entry pad.	\$	11,323
B041-Newton Ctr.			Repair and clean entire exterior metal siding and get ready		
Metal Storage	Wall group	Wall Group 1	for painting 3200sf).	_	
Building			101 painting 320031/1	\$	11,460
B018-Waban	Wall group	Wall group 1	Repair damaged stone at main entrance(50sf).	,	11 501
Library	. 3	0 - 1	· · · · · · · · · · · · · · · · · · ·	\$	11,504
B031-Emmerson	Flooring	Resilient VCT Flooring	Repair/replace areas of VCT flooring that are damaged and	۲	11 (50
Community Center	ļ		worn (20%=1200sf).	\$	11,658
B008-Newton	Parapet		7010		
Police	group	Parapet group 1	Repoint stone parapet cap (70lf).	۲	11 711
Headquarters	<u> </u>			\$	11,711
B028 - Jackson	Egress	Fance Hall Co.	Dealess hattamas des 1105 1111 11		
Homestead	Lighting	Egress Lighting 1	Replace battery packs in all 9 Egress lighting units.	۲	11 072
Museum				Ş	11,873
B032-Lower Falls	Egress	Egress Lighting 1	Replace battery packs in all Egress lighting units.	\$	11,873
Community Center	Lighting	<u> </u>		Ą	11,0/3

DO11 Nouton	Lighting	Lighting controllers group	Install a naw lighting controller unit to control outdoor		
B011 - Newton Corner Library	controllers	Lighting controllers group	Install a new lighting controller unit to control outdoor nighttime settings.		
_	group	1	ingritume settings.	\$	12,004
B028 - Jackson		C: 1 11	Replace exterior 1/2 lite wood door from archive room to		
Homestead	Door group	Single Hung	exterior(1ea). Rework, fit balance of exterior doors(5ea).	\$	12,030
Museum B027-Public				7	12,030
Buildings	Flooring	Carpet Flooring	Remove and replace damaged areas of carpeting as		
Department	lilooning	Carpet Hoornig	required(50% =1200sf).	\$	12,131
B028 - Jackson			Finish TR communications wiring by securing the cabling to	т	
Homestead	Communic	Communication room 1	bring up to BICSI code. Coordinate with an IT plan to bring		
Museum	ation room		the building up to BICSI standards.	\$	12,148
B003-Newton	Classias.	Desilient VCT Flooring			
Senior Center	Flooring	Resilient VCT Flooring	Replace damaged portions of VCT flooring (30%=1700sf).	\$	12,316
B011 - Newton Corner Library	Accessibilit y Item	General Interior	Remove existing drinking fountain and provide a hi-lo drinking fountain in an area that does not interfere with clear maneuvering space or path of travel; Provide door hardware that is operable without tight grasping, pinching or twisting (lever type); Relocate the fire extinguisher so that it does not protrude into the path of travel; Extend the sloped corridor floor so that it does not exceed 5 percent.	\$	12,800
B005-Crafts St DPW Operating Ctr (Stable)	Int. Wall group	Int wall group 1 (brick masonry)	Repair & repoint exposed brick wall (5%=300sf).	\$	12,828
B032-Lower Falls Community Center	Int. Door group	Int. Door group 1	Repair 20% of single hung doors (4ea) and 20% of double hung doors (2ea).	\$	13,040
B027-Public Buildings Department	Ext. lighting group	Ext. lighting group 1	Replace existing exterior lighting fixtures (10 units).	\$	13,192
B024-Jeanette Curtis West Rec Ctr (The Hut)	Ceiling group	Linear Wood Ceiling	Repair (5%=150sf) and paint(3100sf) exposed framing of the gym ceiling.	\$	13,256
B015 - Elliot St. Operations Center	Foundation wall group	Foundation wall group 1	Repair foundation cracking (100 sf); Repair vertical cracks in garage area (50 sf).	\$	13,500
B003-Newton Senior Center	Element group	Cupola	Repair cupola at main roof to stop leaking (120sf foot print area).		13,501
B031-Emmerson Community Center	Stair	Stair 1	Scrape, prepare surface and repaint stair treads with non skid epoxy paint (32r).	\$	13,684
B041-Newton Ctr. Metal Storage Building	Painting group	Painting group 1	Repaint exterior metal wall with a rust inhibiting paint (3200sf).	\$	13,684
B028 - Jackson Homestead Museum	Dom. water piping/insu lation	Dom. water piping/insulation group 1	Provide pipe insulation on all hot water piping in water heater closet.	\$	13,775
B010-Police Annex	group Egress Lighting	Egress Lighting	Replace battery packs in all 9 Egress lighting units.		13,965
B042-Upper Falls Fieldhouse	Painting group	Painting group 1	Repaint exterior concrete wall (1400sf) and underside of concrete overhang (500sf) after all repairs are complete.	\$	14,111
B022-Pelligrini Park Field House	Flooring	Resilient VCT	Remove and replace vct floor in office/restroom areas(1400sf)	\$	14,153

	F: /C l		T	1	1
B026-Burr Park Field House	Fire/Smoke Alarm System	Fire/Smike Alarm	Upgrade Fire/Smoke detectors with audible alarms and strobes to meet ADA requirements	\$	14,927
B029-Crafts Street Garage	Conduit group	Conduit group 1	Replace junction box cover plates throughout interior and exterior of building (est. 3-10) properly secure flexible conduit runs to appropriate locations per code.	\$	15,228
B019 - Nonantum Library	Fire/Smoke Alarm System	Fire/Smoke Alarm System 1	Install audible alarms in toilets for fire alarm system to meet ADA requirements (4ea).	\$	15,366
B013 - Kennard Estate	Dom. water piping/insu lation group	Dom. water piping/insulation group 1	Provide insulation on all domestic water piping.	\$	15,405
B022-Pelligrini Park Field House	Int. Wall group	Walls	Scrape and paint peeling areas of gym walls (10% =800sf). Clean, repair boiler room walls(600sf).		15,488
B011 - Newton Corner Library	Ext. lighting group	Ext. lighting group 1	Replace existing exterior wall pack fixtures (10ea) and add two more to parking area to improve light levels in the parking lot.	\$	15,517
B021-Crystal Lake Bathhouse	Ext. lighting group	Ext. lighting group 1	Add exterior lighting (10 wall pack units) to improve safety & security.	\$	15,517
B019 - Nonantum Library	Int. Door group	Int. Door group 1	Repair, refinish interior doors (50% =9ea).	\$	15,593
B020-Auburndale Library	Ext. lighting group	Ext. lighting group 1	Replace all exterior lighting (6 wall pack units) to improve safety & security. Include a lighting control system to improve energy efficiency.	\$	15,660
B027-Public Buildings Department	Fire/Smoke Alarm System	Fire/Smoke Alarm System 1	Update smoke alarm and strobes to ADA-compliant units.		16,063
B035-Cabot Park Fieldhouse	Accessibilit y Item	Exterior	Rebuild the curb cut at the ramp to be stable, firm, and slip resistant condition; Extend landing at pullside of door to 18"; Provide accessible path to swings and playground that is ADA compliant.	\$	16,100
B013 - Kennard Estate	Int. lighting group	Int. lighting group 1	Upgrade interior lighting system using new energy efficient fixtures.		16,113
B031-Emmerson Community Center	Ceiling group	Acoustical Tile Ceilings	Repair acoustical ceilings (20%=2400sf)	\$	16,316
B008-Newton Police Headquarters	Flooring	Flooring group 2 (vct)	Repair VCT floor as required(30%=1800sf).	\$	16,377
B032-Lower Falls Community Center	Accessibilit y Item	Accessibility - Parking	Install van accessible parking signage; Resurface/Re-grade parking spaces to meet ADA requirements.	\$	16,500
B011 - Newton Corner Library	Communic ation room	Communication room 1	Finish TR communications wiring by securing the cabling to bring up to BICSI code. Coordinate with an IT plan to bring the building up to BICSI standards.	\$	16,588
B005-Crafts St DPW Operating Ctr (Stable)	Egress Lighting	Egress Lighting 1	Replace battery packs in all Egress lighting units.	\$	16,677
B022-Pelligrini Park Field House	Fire/Smoke Alarm System	Fire Alarm System	Upgrade audible fire alarm and strobe to ADA compliance.	\$	16,727

B007-Fire Station	Stair	Stair 1	Install new treads on stairs from 1rst floor to attic (35r).	\$	17,219
#2, West Newton B022-Pelligrini Park	Bearing	Bearing wall group 1	Repoint approximately 5% of the brick façade and replace	7	17,213
Field House	wall group Ext.		roughly 5% of brick.	\$	17,354
B029-Crafts Street Garage	lighting group	Ext. lighting group 1	Convert exterior lighting to LED to reduce frequency of maintenance and improve energy efficiency.	\$	17,408
B010-Police Annex	Dom. water piping/insu lation group	Dom. water piping/insulation group 1	Provide piping insulation on all heating piping in boiler room.	\$	17,659
B001-City Hall		Stone Masonry Walls	Repair stress cracks, infill open core hole, and selectively repoint stone masonry at stone foundation accent wall (50%=2000sf).	\$	17,681
B017- Newton Free Library	Roofing group	Roofing group 1 (hip)	Remove and replace damaged or missing slate tiles (2500 sf). Remove and replace damaged aluminum downspouts with new painted aluminum downspouts to match existing (90 lf). Remove debris and clean gutters along south elevation (200 lf).	\$	17,977
B026-Burr Park Field House	Oil tank group	Oil tank group 1	Remove and properly dispose of two abandonned oil tanks.	\$	18,000
B015 - Elliot St. Operations Center	Fire/Smoke Alarm System	Fire/Smoke Alarm System	Upgrade fire alarm and horn strobes to be ADA-compliant (30 Units).	\$	18,651
B015 - Elliot St. Operations Center	Fan group	Bathroom Exhaust Fans	Provide fan at 75 CFM per toilet/urinal.	\$	20,160
B031-Emmerson Community Center	Wiring group	Wiring group 1	Support communications cables by cable tray system and properly secured per code.	\$	20,663
B012-Gath Pool	Beam and joist group	Beam and Joist Summary	Remove loose spray-on material on underside of first floor slab beams in basement.	\$	21,112
B001-City Hall	Heating piping/insu lation group	Heating piping/insulation group 1	Replace damaged insulation on all heating pipes and install insulation on uninsulated heating pipes.	\$	21,625
B030-Elliot Street Yard Garage	Sprinkler group	Sprinkler group 1	Reconnect disconnected sprinkler pipe serving office space.	\$	21,672
B015 - Elliot St. Operations Center	Cameras group	Cameras group 1	Install camera equipment for security purposes.	\$	22,844
B011 - Newton Corner Library	Dom. water piping/insu lation group	Dom. water piping/insulation group 1	Reroute cold water piping with proper supports and and insulate hot and cold water piping.	\$	22,919
B010-Police Annex	Ductwork group	Ductwork group 1 - AC-1 and AC-2 return	Reroute AC ductwork to meet code requirements and improve space temperature on second floor.	\$	23,123
B011 - Newton Corner Library	Egress Lighting	Egress Lighting	Upgrade entire building to EXIT and Egress code (Estimate 15 units).	\$	23,276
B007-Fire Station #2, West Newton	Other element group	Rear Door Entry Ramp	Install 3x3 entry pads at rear doors(3ea).	\$	23,291
B029-Crafts Street Garage	Wiring group	Wiring group 1	Coordinate a cable tray design with IT Department to support main trunk of cabling for TER to TR closets.	\$	23,918

B011 - Newton	Conduit		Tie back flexible electrical conduit to meet electrical codes		
Corner Library	group	Conduit group 1	and replace rigid conduit.	\$	24,008
			Rewire entire Telcom infrastructure to BICSI code. Secure		,
B011 - Newton	Wiring	Wiring group 1	loose and exposed wiring with conduit bracing and cover		
Corner Library	group		plates.	\$	24,008
	Dom.				
B021-Crystal Lake	water	Dom. water			
Bathhouse	piping/insu	piping/insulation group 1	Provide pipe insulation for hot and cold water piping.		
batimouse	lation	piping/insulation group 1			
	group			\$	24,046
B006-Fire Station	Specialties	Fire Pole Hatches	Repair fire pole drop hatches (4ea)	۰	25 700
#1, Newton Corner	group			\$	25,790
	Dom.				
B019 - Nonantum	water	Dom. water	Provide insulation for all domestic hot and cold water		
Library	piping/insu	piping/insulation group 1	piping.		
,	lation			\$	26,788
B013 - Kennard	group Conduit		Tie back flexible conduit to meet electrical codes and	Ą	20,766
Estate		Conduit group 1		\$	27,576
Newton Corner	group		replace rigid conduit.  Remove abandoned oil tanks and piping through wall and	7	27,370
Library			seal penetrations.	\$	8,148
Library					
	Roof		Clean wood gutters(350lf). Replace missing and dented		
Fire station 2	maintenan		downspouts(90lf). Repair metal roofing at dormers. Scrape	\$	19,467
	ce		and prepare end walls and paint(4ea).		
Burr Park Field	2 (		Repair gutters and downspouts (280lf). Repair step flashing	٠	42.624
House	Roof		at chimney(1ea)	\$	12,624
			Rewire entire Telcom infrastructure to BICSI code. Secure		
B013 - Kennard	Miring		loose and exposed wiring with conduit bracing and cover		
	Wiring	Wiring group 1	plates. There are a number of unsupported wires outside		
Estate	group		the building including some going through trees to supply		
			power to adjacent structures.	\$	27,576
Elliot Garage			Replace Air compresor	\$	10,483
			Repair water damaged first floor perimeter walls		
	Int. Wall		(10%=300sf). Remove basement perimeter plaster & lathe		
B010-Police Annex		Plaster and Lathe Walls	wall, paint wall with water-stop paint and reinstall new		
	group		mold-resistant perimeter drywall (2700sf).		
			moid-resistant perimeter drywaii (2700si).	\$	30,652
B011 - Newton	Fire/Smoke		Update horn strobes to ADA compliant units. Add strobes		
Corner Library	Alarm	Fire/Smoke Alarms	to all offices (20 units).		
Corner Library	System		to an offices (20 anits).	\$	31,034
B031-Emmerson	Int. Door		Repair as required and add panic hardware to single hung		
Community Center	group	Int. Door group 1	doors (50%=10ea) and pairs of doors (50%=4ea).	بر ا	21 664
-, ,	Dom.		, , , , , , , , , , , , , , , , , , , ,	\$	31,661
B022-Pelligrini Park	water	Dom. water	Installing dation on both and cold control of the		
Field House	piping/insu	piping/insulation group 1	Install insulation on hot and cold water piping.		
	lation	]		\$	31,936
B029-Crafts Street	group	Door group 1 (single		۲	31,330
	Door group	hung)	Scrape, prepare surfaces, repaint doors(17ea).	\$	32,995
Garage B028 - Jackson		ilulig)		<u>۲</u>	32,333
Homestead	Int. Door	Int. Door group 1	Refit, minor repair single hung 6 panel doors as		
Museum	group	200. Broak 1	required(35ea).	Ś	35,382
IVIUJCUIII			I	т	,- <b>-</b>

		Double Hung Exterior	Repair, scrape, prepare surface and paint exterior double		
B001-City Hall	Door group	Doors	hung doors and add ADA panic hardware and weather		
		D0013	stripping (9ea).	\$	37,678
DPW Utilites			CO2/NOX ventilation	\$	1,500
DPW Utilites			Replace water heater	\$	1,000
	Water		Verify sufficient combustion air is provided for hot water		
B011 - Newton	heater	Water heater (direct)	heater. Provide openings with dampers per code		
Corner Library	(direct)	group 1	requirements if volume of space does not exceed 50 cubic		
	group		feet per 1,000 BTU/hr input.	\$	38,128
B029-Crafts Street	Cooling	Cooling controls group 1 -	Install programmable thermostat for first floor offices.		
Garage	controls	office thermostat	Provide averaging logic to control RTU.	_	42.004
	group			\$	42,081
	Door group	Overhead Doors	Repair 14x12 (2ea) and 14x14 (2ea) overhead doors as	۲,	F4 070
			required.	<u>ې</u>	51,979
	Int. Wall		Prepare surfaces and repaint interior office walls (7400sf)		
_	group	Int. Wall group 1	and CMU garage walls (4800sf). Finish garage walls and	۲	62,432
Department			paint (2400sf). Repair water damaged, peeling and otherwise deteriorated	Ą	02,432
	Int Mall		areas of interior accoustical tile, plaster & lathe and barrel		
B001-City Hall		Interior Walls	ceilings throughout the building. Scrape, prepare surfaces		
control group 007-Fire Station 2, West Newton 027-Public uildings epartment  control group  Door g  Int. Wa	group		and repaint (20%=14,000sf).	Ś	73,602
			Repair water damaged, peeling and otherwise deteriorated	Υ	75,002
	Ceiling		areas of interior accoustical tile, plaster & lathe and barrel		
B001-City Hall	1	Interior Ceilings	ceilings throughout the building. Scrape, prepare surfaces		
	B P		and repaint (20%=16,000sf).	\$	84,117
			Waterproof exterior foundation walls to minimize water		
	Slab on		infiltration through the walls and slab and Remove &		
B012-Gath Pool	grade	Slabs on Grade Summary	replace the concrete slabs around the entire perimter of		
	group		pools and extending all the way to the back wall of the		
			Gath Pool Building.	\$	105,705