



MEMORANDUM

TO: ROBERT STAULO
FROM: RUSSEL FELDMAN
PROJECT: BRIGHAM HOUSE RENOVATIONS
SUBJECT: PROPOSAL CHANGES
DATE: APRIL 20, 2006

The following summarizes the main changes to the program and design from that which we submitted to the CPC previously. They reflect the feedback we received from the CPC itself and its staff at its public hearing and also at a meeting at the Brigham House, as well as several follow-up discussions with Mike Duff, as recommended by the CPC.

Changes to Exterior Work

1. Eliminate the back porch and stairs and reconfigure the back entry to bring the stairs into the building so that there is no protrusion into the sidewalk area. (Net cost reduction.)
2. Reduce the construction around the back bulkhead as originally proposed and instead slightly enlarge the existing bulkhead to widen the stairs to the basement and make them less steep so that the stair is safer and more serviceable. Provide a metal bulkhead enclosure to that detritus doesn't gather and the hole doesn't pose a danger to anyone walking by. (Net cost reduction.)
3. Replace more of the clapboard siding than originally proposed (85% versus 5%). (Cost increase.)
4. Replace more of the decorative shingles than originally proposed (100% instead of 50%). (Cost increase.)
5. Replace the entire building soffit rather than the 25% originally proposed. (Cost increase.)
6. Replace the entire flat roof area rather than the 5% originally proposed. (Cost increase.)
7. Change gutters to wood from copper lined wood. (Net cost reduction.)
8. Additional weather tightening and trim repair on all existing windows to remain (Cost increase.)

Changes to Interior Work

1. Maintain the interior stair to basement. (Net cost reduction.)
2. Create a new MAAB compliant bathroom in the Meeting/Tech Room area rather than as originally proposed at the basement stair area. (Net cost reduction from original proposal.) This solution is slightly more expensive than reconfiguring the

Robert Staulo
Brigham House Scope Changes
April 19, 2006
Page 2 of 2

existing bathroom in its existing location (perhaps \$2500) but we feel this is a relatively minor expenditure that results in a very significant benefit to the building overall.

3. Replacement of existing furnace and burner with limited work on system distribution and controls. (Cost increase.)
4. Chimney cleanout and repair. (Cost increase.)
5. Reduction of new interior doors and trim. (Cost reduction.)
6. Elimination of kitchenette cabinet and sink. Plumbing provided to area for future installation. (Cost reduction.)

General Cost Changes

1. Increase construction inflation from Spring 2006 Fall 2006. (2.5% additional.)
2. Reduce project contingency from 15% to 10%. (Cost reduction.)

END

Renovations to Brigham House
20 Hartford Street
Newton Highlands

Unifomat Ref. No.	System/Component	Specifications	Unit	No. Units	Unit Cost	Sub Total	Total
A Substructure							
B Shell							
A10	Foundations						\$2,447
A1010	Standard Foundations						
Foundation Walls	Brick Foundation Wall Repointing	s.f.	125	\$5.25	\$656		
Foundation Walls	Footing for new foundations	l.f.	25	\$56.00	\$1,400		
Foundation Walls	Foundation wall, reinf, filled core block on footing	s.f.	0	\$16.50	\$0		
Foundation Walls	Cut and frame new bulkhead	s.f.	40	\$9.76	\$390		
B10	Superstructure						\$8,085
B1010	Floors and Walls						
Foundation Construction	2x8 wood joists @ 16 in. O.C.	s.f.	72	\$1.75	\$126		
Stairs	Build in place, pine treads plus framing porch plus rear stair	riser	10	\$74.00	\$740		
Egress Stair Framing	Oak rails, both sides	t.f.	12	\$110.00	\$1,320		
Ornamental Rail at Flat Roof	6x6 pine posts, rails and balusters; flashing	l.f.	72	\$32.00	\$3,024		
Landing Superstructure	2x10 12-oc wood frame with plywood subfloor	s.f.	16	\$3.80	\$61		
Exterior Wall	2x6 studs, plywood, R1.1 batt insul, cedar siding	s.f.	72	\$10.61	\$764		
Arcaway Stairs	New treads and risers to basement stairs	flight	1	550	\$550		
Window / Infill	New interior insulated shutters over window/lower sash	ea.	0	\$125.00	\$0		
Arcaway cover	New metal bulkhead door and frame to cover basement entry	item	1	\$1,500.00	\$1,500		
Floor Construction	Reframe basement for stair, floor infill	item	0	\$750.00	\$0		
Basement	Concrete slab	s.f.	0	\$2.88	\$0		
Bulkhead Roof Cover	Posts, framing, deck	item	0	\$1,500.00	\$0		
B1020	Roof Construction						\$2,955
Flat roofs	Replace existing flat roof	s.f.	525	\$4.50	\$2,363		
Pitched roofs	Repair existing along gutters, valleys 5%	s.f.	45	\$13.16	\$592		
Back porch roof	Framing and roofing for porch and stairs	s.f.	0	\$38.16	\$0		
Bulkhead Roof Cover	Roofing framing; operable with frame	s.f.	0	\$38.16	\$0		
B20	Exterior Closure						\$98,561
B2010	Exterior Walls						
07210	Soffits	Scrape soffits, cover with 1/8" plywood for painting 100% area	l.f.	1260	\$25.00	\$31,500	
	Fascia	Replace 100% fascia boards	s.f.	151	\$10.00	\$1,510	
	Cornices	Reconstruct deteriorated corners, whole assembly	ea.	9	\$500.00	\$4,500	
	Siding preparation	Scrape all siding, clapboards, trim	s.f.	3,424	\$3.50	\$11,984	
	Repair siding	New 18' #1 red cedar, 4" exposure, 85% of area	s.f.	2,910	\$6.00	\$17,462	
	Repair siding	Cut shingles replacement at aprons, 100% area	s.f.	712	\$7.50	\$5,340	
	Columns	Strip columns and capitals	item	2	\$2,500.00	\$5,000	
	Columns	Epoxy consolidate and repair of capitals	item	2	\$1,000.00	\$2,000	
	Paint siding and trim	Oil Primer and two coats, two colors, exterior latex	s.f.	3,424	\$3.25	\$11,128	
	Paint premium	Multi color detailing, 4 colors	s.f.	3,424	\$1.50	\$5,136	
	Paint premium	Ornamental Railing	l.f.	72	\$7.50	\$540	
	Insulation	Fiberglass batts roots under new roof areas only, R19 average	s.f.	72	\$1.83	\$132	
	Insulation	Blow in fiberglass insulation, 6' R13	s.f.	3,424	\$0.68	\$2,328	
	Bulkhead Roof Covering	Paint deck and trim, oil primer and two coats	item	0	\$250.00	\$0	
B2020	Exterior Windows						\$8,848
900-04-40	Window Preparation	Careful scraping and reglazing	ea.	38	\$110.00	\$4,180	

**Renovations to Brigham House
20 Hartford Street
Newton Highlands**

Unifromat Ref. No.	System/Component	Specifications	Unit	No. Units	Unit Cost	Sub Total	Total
08510	Window frames	Miscellaneous trim repair and patching	ea.	6	\$75.00	\$450	
08510	Window repair	Double hung, double glazed wood to replicate existing	ea.	4	\$735.00	\$2,940	
08510	Window storm	Repair existing decorative window	ea.	1	\$300.00	\$300	
		Custom size fixed storm windows; painted finish	ea.	5	\$195.60	\$978	
B2030	Exterior Doors	Scrape & sand, wood	s.f.	40	\$0.55	\$22	
	Prep Doors	Paint & 2 coats exterior latex, both sides	s.f.	40	\$28	\$1,120	
	Entry Door	New wood door, frame and hardware	ea.	1	\$1,600	\$1,600	
	Bulkhead	Steel security door	s.f.	1	\$450.00	\$450	
							\$3,192
B30	Roofing						\$7,320
B3010	Roof Coverings	EPDM fully adhered on new deck all flat roof areas	s.f.	525	\$4.58	\$2,406	
	Flat roofs	Asphalt shingle to match existing	s.f.	0	\$4.61	\$0	
	New roof	Patch existing asphalt at gutters, valleys and eaves, 10% wood clear, hemlock or fir, 4"x5"	s.f.	278	\$4.61	\$1,282	
	Existing roof	copper corrugated	l.f.	151	\$12.55	\$1,895	
	Gutters		l.f.	151	\$11.50	\$1,737	
	Downspouts						
C	Interiors						
C10	Interior Construction						\$20,611
C1010	Interior Partitions	Structural framing for new spans at bay	item	1	\$400.00	\$400	
		New infil at doors	ea.	2	\$57.75	\$116	
		New partitions, 2x4 studs, GWB taped both sides	s.f.	990	\$1.99	\$1,970	
		Open existing partitions, refinish floors & cigs	ea.	4	\$150	\$600	
		Case openings with decorative trim	opening	7	\$800	\$5,600	
C1020	Interior Doors	New doors, 4 panel oak to match existing incl hardware	ea.	4	\$850	\$3,400	
		New doors, reuse existing into new frames incl hardware	ea.	2	\$400	\$800	
		New pocket doors, 6' wide panel wood	ea.	0	\$750	\$0	
C1030	Interior Specialties	Bathroom accessories: towel, soap, toilet, sanitary, mirror, hook	set	1	\$1,500	\$1,500	
		Accessibility set: grab bars, mtd with blocking	set	1	\$225	\$225	
		Custom carpentry repair: stair rail and ballusters	item	1	\$6,000	\$6,000	
		Wallcovering for hanging art/painting/others specialty surfaces	s.f.	0	\$8.50	\$0	
		Kitchenette cabinet	ea.	0	\$750.00	\$0	
							\$41,646
C30	Interior Finishes						
C3010	Interior Finishes	Gypsum walls, ceilings	s.f.	1,152	\$2.45	\$2,822	
		Gypsum walls, ceilings	s.f.	378	\$1.38	\$520	
		Gypsum walls, ceilings	s.f.	9,444	\$0.50	\$4,722	
		Painting	s.f.	10,596	\$0.55	\$5,785	
		Exterior wall finish	s.f.	3,424	\$1.24	\$4,246	
		Interior Floor Finishes					
C3020		Vinyl wallpaper as vapor barrier, exterior wall surfaces					
		1/2 in. Bluebd cigs, skim coat plaster on vibration board for sound isolation					
		1/2 in. Bluebd walls, skim coat plaster					
		patch existing walls and ceilings					
		walls- roller, prime & 2 coats					
		Vinyl wallpaper as vapor barrier, exterior wall surfaces					
		Woodwork sanding, touchup stain, varnish					
		Wood flooring - strip oak patch/infil existing 10%					
		Wood flooring - strip oak patch new floor					
		Refinish existing wood					
		Level existing deck for floor					

Renovations to Brigham House
20 Hartford Street
Newton Highlands

Unified Ref. No.	System/Component	Specifications	Unit	No. Units	Unit Cost	Sub Total	Total
	VCT	s.f.	35	\$3.03	\$106		
D	Services						
D20	Plumbing Systems	New bathrooms: 2 fixtures incl piping and rough in New kitchenette supply piping, rough out only New bathroom supply piping Relocate existing fixtures Plumbing demo Kitchenette sink Craft sink and cabinet	set set ea bathrm ea ea	1 1 0 1 0 1	\$4,052 \$1,500 \$4,000 \$1,250 \$250 \$250	\$4,052 \$1,500 \$4,000 \$1,250 \$250 \$250	\$10,052
D30	HVAC Systems	New burner and furnace Chimney flue cleanout and repair Duct rehaby/modificatin	ea item item	1 1 1	\$3,400 \$400 \$750	\$3,400 \$400 \$750	\$4,550
D50	Electrical Systems	New light at entries Fluorecent overhead lighting Overhead light and circuit New outlets Distribution Demo Light Fixtures Communication & Security Systems	ea. ea. ea. ea. budget budget	2 10 1 17 1 1	\$250 \$308 \$325 \$115 \$2,500 \$500	\$500 \$3,080 \$325 \$115 \$2,500 \$500	\$8,860
D5020	Lighting & Branch Wiring	Emergency lighting and alarms [audible, visual]	budget	1	\$5,000	\$5,000	\$5,000
16500	Rehabilitated Light Fixtures New Light Fixtures Bulkhead Roof Covering Distribution Demo Light Fixtures						
D5030	Special Electrical Systems	Not Used					
D5040	Special Electrical Systems	Emergency lighting and alarms [audible, visual]	budget	1	\$5,000	\$5,000	\$5,000
	Equipment & Furnishings						
E10	Equipment	Not Used					\$0
E20	Furnishings	Not Used					\$0
	Other Building Construction						
F10	Special Construction	Not used					\$0
F20	Selective Demolition						\$451
F2010	Building Elements Demolition Windows & Doors Excavate foundation wall Gutters & Downspouts	Remove windows and doors Hand excavate at egress stair foundation Remove gutters, damaged soffits & fascia	item lf. lf.	0 0 151	\$75.00 \$80.00 \$1,00	\$75.00 \$80.00 \$151	

**Renovations to Brigham House
20 Hartford Street
Newton Highlands**

Unifromat Ref. No.	System/Component	Specifications	Unit	No. Units	Unit Cost	Sub Total	Total
G10	Stairs	Remove basement access stair treads	item	1	\$50.00	\$50	
	Bulkhead	Remove bulkhead walls and floor	item	1	\$150.00	\$150	
	Landscape	Remove plantings at rear patio	item	1	\$100.00	\$100	
	Basement	Excavate for new basement area and stair, hand excavate	c.y.	0.00	\$25.00	\$0	
G Building Sitework							
G10	Site Preparation	Back entry, 1x4 mahogany Custom design architectural grade hardwood Remove concrete walkways Repair wooden ramp Repair and reset rails and balusters Construct new concrete bulkhead stairs to basement, reinf conc	s.f. l.f. item budget l.f. flight	16 12 1 121 1	\$4.00 \$75 \$150 \$6,000 \$12.50 \$4,386	\$64 \$900 \$150 \$6,000 \$1,513 \$4,386	\$13,013
G20	Site Improvements	Patch sidewalks around rear bulkhead No work New fill and grading at old bulkhead Relandscape back patio, perimeter as required	item l.f. s.y. budget	1 0 0 1	\$400.00 \$0.00 \$2.44 \$2,500	\$400 \$0 \$0 \$2,500	\$2,900
Subtotal Construction Subcontracts, Unadjusted							
	Location Factor	15.0%					\$35,773
	General Conditions (Overhead and Profit) per Means	25.0%					\$68,565
	Filed Sub-bid Premium	15.0%					\$41,139
	Inflation to bid premium (fall 2006)	9.0%					\$34,557
TOTAL ESTIMATED CONSTRUCTION COST							
	Architect/Engineering Fee	12.8% of construction cost					\$53,445
	Reimbursable Expenses	10.0%					\$5,345
	Design Contingency	0.0%					\$0
	Change Order Contingency	10.0%					\$41,852
TOTAL ESTIMATED PROJECT BUDGET							
Project Cost Summary							
	Construction Cost						\$419,000
	Architect/Engineering Fee						\$53,000
	Contingencies and Reimbursables						\$47,000
TOTAL ESTIMATED PROJECT BUDGET							
\$519,000							

TB


TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
TELEPHONE: 617-451-2444
FAX: 617-451-2444

THE BRIGHAM HOUSE
Renovations and Alterations to
20 Hartford Street, Newton Highlands, Massachusetts 02461

CONTRACTOR	Schematic Design	Architect	DATE OF ISSUE	DATE OF REVIEW	SPONSOR	MFG	RHV
COHESIVE	02.07.05	02.16.06	02.07.05	02.07.05	Newton Highlands, Massachusetts 02461	1/8'-0"	1/8'-0"

TBA PROJECT # 9981

A-1





TBA ARCHITECTS INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
www.tbak.com

THE BRIGHAM HOUSE
Renovations and Alterations to
20 Hartford Street
Newton Highlands, Massachusetts 02461

REVISI

ONS

02/07/05

DATE OF ISSUE

02/16/06

MEETING NOV


SPONSOR

A-2

NOT FOR CONSTRUCTION

TECHNICAL • TTB

FIRST FLOOR PLAN
Schematic Design
Scale 1:8"






TBA
ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
INTEGRATED DESIGN
TECHNOLOGY / CONSTRUCTION
MANAGEMENT

THE BRIGHAM HOUSE
Renovations and Alterations to
20 Hartford Street, Newton Highlands, Massachusetts 02461

MSF
DATE OF ISSUE
02.16.06
02.07.05
REVISIONS
SPECIFICATION
NUMBER
September 1, 2004
Newton Highlands, Massachusetts 02461


SCHEMATIC DESIGN
Second Floor Plan
A-3
CONTRACT DOCUMENT
PROJECT NUMBER





TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR
INTERFACADE
TECHNICAL SERVICES
PROJECT MANAGEMENT

RENOVATIONS AND ALTERATIONS TO	THE BRIGHTHAM HOUSE	20 HARRIORD STREET	NEWTON HIGHLANDS, MASSACHUSETTS 02461
DATE OF ISSUE	02.07.05	SPONSOR NUMBER	1,2004
VERSIONS	02.16.06	MSR	MM
REVISIONS	02.16.06	SPONSOR	DATE OF ISSUE
SCALE	1'-0" = 3'-0"	NOT FOR CONSTRUCTION	PROJECT # 0000





TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
PROJECT MANAGEMENT
www.tbarchitects.com

THE BRIGHAM HOUSE
Renovations and Alterations to
20 Hartford Street
Newton Highlands, Massachusetts 02461

REV 02461

DATE OF ISSUE
02.16.06

SPONSOR
SupremeCo., Ltd.

REVISIONS
02.07.05

ARCHITECT
KIVI

DESIGNER
MS

CONTRACTOR
MS


SCALE
0'-0"

ROOF PLAN

A-5

SCHEMATIC DESIGN

NOT FOR CONSTRUCTION



GENERAL NOTES:

1. Fiberglass batt insulation, R19
2. Patch existing at gutters, valleys & eaves

Pitched Roofs
2 X 12 16" OC @ 4:12
asphalt shingle & paper

Flat Roof
EPDM to match existing



TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE,
INTERIOR DESIGN
NCORPORATED 1978
TBA ARCHITECTS, INC.
100 CHURCH ST., SUITE 200
NEW YORK, NY 10007
TEL: (212) 736-1000 FAX: (212) 736-1001
www.tba.com

THE BRIGHAM HOUSE
Renovations and Alterations to
20 Hartford Street
Newton Highlands, Massachusetts 02461

Newton Highlands, Massachusetts 02461
20 Hartford Street
DATE OF ISSUE: 02/16/06
SPECIALIST: SPARKER, I., 2004
REVISIONS: 02/07/05
PAGE: 10
NOT FOR CONSTRUCTION
THIS PROJECT IS FOR

Front Elevation (Hartford Street)
Schematic Design
COMMITTEE: A-6

GENERAL NOTES:


1. Replace all fascia boards
2. Re-construct deteriorated cornices
3. Scrape soffits, cover w/ plywood for painting
4. New gutters and downspouts, as noted on plans

Demolition Notes:

- remove windows and doors
remove gutters, damaged soffits & fascia
remove siding
remove damaged apron sheathing

Railing
Install new railing on flat roof

Windows
scrape and reglaze
misc trim repair & patch
New able hung glass glazed wood
repair decorative window
fix storm windows, as noted



Siding
Replace all lapboards and shingles
Install new 18 # 1 red cedar clapboards.
Replace damaged apron sheathing.
Scrape trim and ornamental details.
Replace damaged elements.
Prepare for paint.
Paint all exterior wood.

Columns
strip columns & capitals
epoxy consolidate & repair capitals
Doors
scrape & sand wd
paint [both sides]



TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
TELEPHONE 508.865.2070 FAX 508.865.2071
www.tbarchitects.com

THE BRIGHTHAM HOUSE
Renovations and Alterations to

Newton Highlands, Massachusetts 02461

20 Hartford Street

Persons

Spelman, L., 204

Date of Issue

02.07.05

M.S.

MS-A/HV

Architect

02.16.06

Scale

0'-0"

8'

1'-0"

1'-8"

1'-8"

1'-0"

A-9

Comments

2001

NOT FOR CONSTRUCTION

The Project Name

GENERAL NOTES:


1. Replace all fascia boards
 2. Re-construct deteriorated cornices
 3. Scrape soffits, cover w/ Plywood for painting
 4. New gutters and downspouts, as noted on plans
- Demolition Notes:
- remove windows and doors
 - remove gutters, damaged soffits & fascia
 - remove siding
 - remove damaged apron sheathing

Columns

- strip columns & capitals
- epoxy consolidate & repair capitals

Access Ramp

- rebuild or repair rails, replace bannisters, paint





TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
INTERIOR FINISHES
TELEVISION STUDIO DESIGN
THEATRE STAGE DESIGN
WATER FEATURES

THE BRIGHAM HOUSE
Renovations and Alterations to
20 Hertford Street, Newton Highlands, Massachusetts 02461

DATE OF ISSUE 02.16.06
SPEAKER 1, 2004
REVISED 02.07.05
MFG. MHW
DRAWN BY J. H. H.
SCALE 1/8" = 1'-0"
REVISIONS

REAR ELEVATION
Schematic Design
COPRIGHT 2004
NOT FOR CONSTRUCTION
PROJECT #108

A-8

GENERAL NOTES:

1. Replace all fascia boards
 2. Re-construct deteriorated cornices
 3. Scrape soffits, cover w/ plywood for painting
 4. New gutters and downspouts, as noted on plans
- Demolition Notes:
remove windows and doors
remove gutters, damaged soffits & fascia
remove siding
remove damaged apron sheathing

Patch existing gutters, valleys & eaves


Siding

Replace all clapboards and shingles
Install new 18 #1 red cedar clapboards.
Replace damaged apron sheathing,
Scrape trim and ornamental details.
Replace damaged elements.
Prepare for paint.

Patch existing gutters, valleys & eaves
Paint all exterior wood.

Access Ramp

rebuild or repair rails, replace balusters, paint
new concrete bulkhead
new concrete stairs



- Pitched Roof
Asphalt shingles to match existing
Fiberglass batt insulation, R19 (attic)
- Flat Roof
Patch existing
EPDM adhered on new deck over Porch infill
- Railing
Install new railing on flat roof
- Back Door
New door
New roof w/ ornamental brackets
New concrete step
- infill window
- Bullhead



TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
EXTERIOR DESIGN
TEL. 508.865.1000 FAX 508.865.1001
www.tba.com

THE BRIGHAM HOUSE
Renovations and Alterations to
Newton Highlands, Massachusetts 02461

20

Hartford Street

Newton Highlands, Massachusetts 02461

Revisions

20A

Date of Issue

02.16.06

Supplement

1

Architect

NHIV

MSF

Architect

MSF

Architect

NHIV

Elevation
Right Side

Schematic Design

A-7

NOT FOR CONSTRUCTION

GENERAL NOTES:

1. Replace all fascia boards
2. Re-construct deteriorated cornices
3. Scrape soffits, cover w/ plywood for painting
4. New gutters and downspouts, as noted on plans


Demolition Notes:

- remove windows and doors
- remove gutters, damaged soffits & fascia
- remove siding
- remove damaged apron sheathing

Railing

Install new railing on flat roof

- Siding
- Replace all clapboards and shingles
 - Install new 18 1/4 red cedar clapboards.
 - Replace damaged apron sheathing.
 - Scrape trim and ornamental details.
 - Replace damaged elements.
 - Prepare for paint.
 - Paint all exterior wood.



Columns
strip columns & capitals
epoxy consolidate & repair capitals

Windows
scrape and reglaze
miss trim repair & patch
New double hung double glazed wood [3rd flr]
repair decorative window

Access Ramp
rebuild or repair rails,
replace balusters, paint


Roof




TBA ARCHITECTS, INC.
PLANNING
ARCHITECTURE
INTERIOR DESIGN
LANDSCAPE ARCHITECTURE
INTERIOR CONTRACTING
GENERAL CONTRACTING
PROJECT MANAGEMENT

THE BRIGHAM HOUSE
20 Hartford Street
Newton Highlands, Massachusetts 02461
Renovations and Alterations to


DATE OF ISSUE	02/07/05	SPRINGER, L. ZOON	REGIONS
NAME OF DRAWER	0216.06	NAME	SCALE
NAME OF PROJECT	A-10	1-1 = 8'/-	NOT FOR CONSTRUCTION
CONTINUED	2004	SHEET	PROJECT #A-10




Right Side Elevation



Left Side Elevation



Front (Hartford Street) Elevation



Rear Elevation