
-- analysis CP-funded -- Board order 458-05, 18 Sept 06 -- total cost \$21,059





BUILDING ENVELOPE EVALUATION CRAFT STREET STABLE DPW FACILITY Newton, MA

AUGUST 29, 2008

Members of the American Institute of Architects and USGBC107 Audubon Rd., Bld. 2, Suite 300, Wakefield, MA 01880P 781.245.8400 • F 781.245.9372 • css@cssarchitects.com • www.cssarchitects.com

TABLE OF CONTENTS

CSS Architects Inc. Wakefield, Massachusetts

BUILDING ENVELOPE EVALUATION

Crafts Street Stable – DPW Facility Newton, MA

August 26, 2008

Section No.	<u>Title</u> <u>Page Numbers</u>
1.	Executive Summary 1
2.	Existing Conditions2-5
3.	Recommendations
4.	Cost Estimate
5.	Appendixes
	Appendix I – PhotographsI-01 – I-18
	Appendix II – Schedule, Window Details II-01 – II-03
	Appendix III– Window and Door Types A-7
	Appendix IV – Elevations and PlansA-1 thru A-6
	Appendix V – Consultant's Report

EXECUTIVE SUMMARY

INTRODUCTION

CSS Architects Incorporated was retained by The City of Newton to conduct a building envelope evaluation and A.A.B compliance review of the Crafts Street Stable Building that is presently being used as a DPW Facility at 92 Crafts Street, Newton, MA. The objective was to review the existing building envelope and handicap compliance. This report summarizes the findings from CSS Architects Inc and Thompson & Lichtner's inspection of the building envelope; comprised of exterior masonry, slate roofs, copper gutters and downspouts, wood windows and doors and handicap accessibility. The report provides recommendations for repairs and an estimate of repair costs.

COST ESTIMATE

BUILDING ENVELOPE EVALUATION

Crafts Street Stable- DPW Facility Newton, MA

18 July 2008

ITEM

ESTIMATED COST

RECOMMENDATION A-WINDOWS

1. Replace seventy five (75)windows 120,000

RECOMMENDATION B- DOORS

1.	Replace six (6)Type A doors 15,000)
2.	Replace four (4) overhead doors	0
2.	Rebuild /restore two door canopies 6,000	

See Consultants Report for Cost Estimate

Note: Costs do not include General Conditions (10%), Insurance/bonds (2%), Overhead and Profit(15%)

ESTIMATED COST ABOVE ITEMS A, B \$161,000.00

ESTIMATED COST – CONSULTANT REPORT ITEMS A-B

TOTAL ESTIMATED COST (including G.C.,I &B, O&P)...... \$544,533.00



0

MD Thompson & Lichtner

CSS Architects Re: 92 Crafts Street, Newton, MA August 26, 2008 Page C.1

The following is our estimated cost to perform the repair program outlined in this report.

ITEM

ESTIMATED COST

A. SLATE ROOFS

- Replace all open copper valleys approximately 160 1. lineal feet to include replacement of deteriorated wood decking and installation of Ice & Water Shield on deck.
- 2. Replace copper cricket, copper flashing, and copper pans at the chimneys including replacement of deteriorated wood decking and installation of Ice & Water Shield.
- 3. Installation of copper drip edge with Ice & Water Shield to gable end on the front elevation.
- 4. Replace all copper vent pipe flashing and Ice & Water Shield at vent pipes.
- 5. Replace damaged and missing copper down spouts.
- 6. Repair/replace copper hip/ridge capping and fascia/soffits and add fasteners. Replace wood beneath caps.
- 7. Replace existing snow guards with new premanufactured snow guards.
- 8. Replace 500 damaged, deteriorated, and missing slates.

The total cost estimate for the above items 1 through 8 should range between

\$90,000 - \$100,000



Thompson & Lichtner

CSS Architects Re: 92 Crafts Street, Newton, MA August 26, 2008 Page C.2

ITEM

ESTIMATED COST

Β. BRICK MASONRY

1.	Total for repointing all four elevations only defective mortar joints	\$137,025
2.	Step Crack Repairs	
	Option 1 – Sealant	\$650
	Option 2 – Pointing	\$1,100
	All four elevations	
3.	Spalled Brick Replacement	
	All four elevations	\$5,000
4.	Repair of concrete and coating of concrete at rear	¢10.000
	elevation	\$18,000

GRAND TOTAL RANGE OF \$251,775 TO \$261,125