Unit #	Location on Building	Project
	34	Windows
	49	Windows
	25 West (rear) elevation, immediately north (on side away from High St)	Windows
	41	Windows
	45	Windows
	44 Fourth floor-blocked by trees	Windows
	21 Faces Pettee St	Windows
	46	Windows
	27 Street facing unit	Windows

22 (1) faces out towards High; Windows (7) in rear of building somewhat towards High 47 Fourth floor front unit Window Gutters and flashing Rear center roof of building 32 Rear (8) windows; Green St Windows Side (2) Gutters, flashing, window trim, Rear center roof of building valley

Proposed	Approved
Replace (5) windows, wood double hung with same style	(5) replacement windows
Replace (1) window	-
Replace (4) double hung wood windows with in-kind wood Pella architect series. To inlude full wood painted 7/8" muntins.	(4) replacement windows
Replace (3) windows, double hung, wood windows, painted to match current exterior color, muntin style to match existing pattern, double pane insulated	(3) replacement windows
giass	
glass Replace (3) windows Fiberglass - in kind	(3) replacement windows Fiberglass - in kind
Replace (3) windows	Fiberglass - in kind (6) replacement windows. Must be
Replace (3) windows Fiberglass - in kind Replace (6) windows, in kind, with white aluminum clad, SDL grilles with permanent spacebar 7/8" profile. All exterior trim to	Fiberglass - in kind (6) replacement windows. Must be Pella 400 architect series, wood, NO
Replace (3) windows Fiberglass - in kind Replace (6) windows, in kind, with white aluminum clad, SDL grilles with permanent spacebar 7/8" profile. All exterior trim to	Fiberglass - in kind (6) replacement windows. Must be Pella 400 architect series, wood, NO

Replace (8) windows	(8) replacement windows
Replace (1) window with vinyl	(1) window (not vinyl)
copper	Copper in kind
Replace (10) windows	(10) replacement windows

Replace in kind valley, replace in kind gutter, replace in kind base flashing, replace masonry flashing Replace gutters, step and counter flashing, window trim in kind

Additional Information & Details About Approved	Certificate Issued	Date
(2) Pella Architect, double hung, 1/1, wood, 49"x68 1/2", vent-equal sash 50:50 Top:Bot Sash split monumental hung; (3) Pella architect, double hung, 1/1, wood, 42 3/4"x68 1/2", vent-equal sash 50:50 Top:Bot Sash Split Double Hung	C.N.A	2002.04.17
(1) Pella 3/2	Hardship	2003.04.10
(2) Pella Architect, double hung, 2/2 - centered between (2) (half width) Pella architect, double hung, 1/1. Wood, 7/8" width muntins.	C.N.A	2003.08.18
(3) Pella Architect, wood simulate true divided light, muntin bars (grilles), 2/2	COA	2005.11.15
- (2) Pollo Imporvio Doublo Hung 2/1 /2 25"v50" white fibergless	C.N.A	2007.12.24
(3) Pella Impervia, Double Hung, 3/1, 42.25"x59", white, fiberglass	C.N.A	2010.06.22
(1) Pella Architect, Monumental Hung Double Hung, 2/2, 49.25"x68.5", white 3-11/16", standard EnduraClad; (1) Pella Architect, Precision Hung Double Hung, 1/1, 19.5"x65.75", white, Standard Euraclad; (1) Pella Architect, Precision Hung Double Hung, 2/2, 42.75"x68.5", white, standard enduraclad; (2) Pella Architect, Monumental Hung Double Hung, 2/2, 49.25"x68.5", white, 3-11/16", standard enduraclad; (1) Pella Architect Precision Hung Double Hung, 2/2, 42.75"x68.5", white, standard enduraclad.	COA	2010.11.10
(3) Pella Architect, precision double hung, 2/2, 43" x 47.5", Standard clad white prime, luxury edition wood; (3) Pella architect, precision double hung, 1/1, 43"x 47.5", wood, white	C.N.A	2012.05.30
All- Renewal by Andersen and white in color. Living Room: (2) double hung 1. two over two - current openning 49 $1/2 \times 68 5/8$ with exact order 49 $1/16 \times 68 1/4$; 2. one over one - current openning 19 $1/2 \times 66 3/8$ with exact order 19 $1/16 \times 65 15/16$; Office: (2) double hung (two over two) 1&2. current openning 49 $1/2 \times 68 5/8$ with exact order of 49 $1/16 \times 68 1/4$; Master bedroom: (2) double hung (two over two) 1&2. current openning 49 $1/2 \times 68 5/8$ with exact order of 49 $1/16 \times 68 1/4$.	Resolved (see notes)	2013.02.14

Option A: Lowes - All 8 were 850 Architect Series (3) Pella double hung, 2/2, aluminum clad wood, 43"x68 1/2", white; (2) Palla double hung, 2/2 (with divider on all 4 panes), aluminum clad wood, 49 1/2" x 68 1/2", white; (1) Pella double hung, 1/1, aluminum clad wood, 23 1/2"x 68 1/2", white; (2) Pella double hung 2/2, aluminum clad wood, 39" x 57", white. Option B: Home Depot - (3) American Craftsman double hung, 2/2, 43"x68 1/2", 8500 series white; (2) American Craftsman double hung, 2/3, 49 3/8" x 68 1/2", 8500 series white, vinyl; (1) American Craftsman double hung, 1/1, 23 1/2" x 68 1/2", 8500 series white; (2) American Craftsman double hung, 1/1, 39" x 57", 8500 series white.	C.N.A	2013.10.17
(1) Harvey Majesty aluminum clad wood window, double hung with a 3/2 profile	COA	2014.05.08
2002 Revere red copper; flashing: Mullane Model 500 three pipe system	C.N.A	2014.10.08
All- Renewal by Andersen - Dining room : (2) double hung windows - (2 over 2) current opennings 39x52 3/4 and exact order 38 9/16 x 52 3/8, white; Living room : (2) double hung (2 over 2) opennings : 1. current 49 1/2 x 68 3/4 with exact order 49 1/16 x 68 3/8; 2. current 43 x 68 3/4 with exact oder 42 9/16 x 68 3/8 color white; Living Room : (2) picture windows (3 rows 2 columns) 1. current openning 49 1/2 x 33 3/4 exact order 49 1/16 x 33 3/8; 2. current openning 43 x 33 3/4 exact order 42 9/16 x33 3/8, color white; bedroom : (2) double gung (2 over 2) both current openning 49 1/2 x 68 3/4 exact order 49 1/16 x 68 3/8 color white; bedroom : (2) picture windows (3 rows 2 columns) 1. current openning 49 1/2 x 33 3/4 with exact order of 49 1/16 x 33 3/8; 2. current openning 23 9/16 x 33 3/4 with exact order 23 1/8 x 33 3/8; all color white	COA	2016.07.10

C.N.A 2016.09.27

Gutters: copper; window trim: white PVC

Reason for Decision and other comments/notes
Replacement in Kind
No quorum; commission requested that the
Replacement in Kind
Appropiate
Replacement in Kind Not visible
Appropiate

Oblique and distant view from public way, brand and model consistent with others installed in bldg.

Resolved that the owner provide a comparative analysis of Pella vs. Renewal window profiles. If Andersen makes a Renewal weindow that matches the Pella window that has been installed, then the application will be approved. Staff signed off after more info submitted on 2013.03.18

Consistent with other replacement window specs in building; minimally visible from public way. Could go with either Lowe's or Home Depot Specs - we are not sure which one they chose.

Appropiate - matches other windows on building

Replacement in Kind

Appropriate - based on the fact that the replacement windows will be reproductions of Anderseon Renewal windows based on the fact they have been previously approved, including the size of the muntins

Replacement in Kind