School Building Committee Franklin Elementary School Existing Condition Study July 7, 2022

H M HMFH ARCHITECTS

Existing Site Plan Study



SITE STATISTICS

5.45 Acre Site760' Street FrontagePUB Zoning

Surrounding Zoning RES3

- 1* Fields in poor shape.
- 2* Ramp does not meet current ADA Code



Proposed Program for New Franklin School


		PROPOSED FRANKLIN		
ROOM TYPE		ROOM	# OF	area
CORE ACADEMIC SPACES				21,300
(List classrooms of different sizes				
Pre-Kindergarten w/ toilet				
Kindergarten w/ toilet		1,200	4	4,800
General Classrooms - Grade 1-5		900	18	16,200
ELL Program		300	1	300
SPECIAL ED, RESOURCE & SUPPORT SPACE				7,650
(List rooms of different sizes separately)				
Bridge Program Classroom		900	2	1,800
Bridge Safe Room		100	2	200
Bridge Specialist Office		150	2	300
Bridge Breakout Room		125	2	250
Learning Centers (K-2; 3-5)		450	2	900
Breakout Rooms (small group/individual		125	6	750
OT/PT		475	1	475
OT/PT Office		150	1	150
Safe Room / Mindful Room (1/ academic		100	2	200
Speech + Language		300	1	300
Inclusion Facilitators (office for 6 adults;		250	1	250
Team Specialist + IEP Conf Room (12		400	1	400
Psychologist (Office, testing, therapy,		150	1	150
Social Worker (Office, testing,		150	1	150
Reading Program/ Literacy Room		900	1	900
Literacy Specialist Offices		175	1	175
Math Coach		150	1	150
SEL Coach		150	1	150
ART & MUSIC				2,575
Art Classroom - 25 seats		1000	1	1000
Art Workroom w/ Storage & kiln		150	1	150
Music Classroom / Large Group - 25-50		1200	1	1200
Music Practice / Ensemble (Groups 4-		150	1	150
Music Practice / Ensemble (Groups 4-	•	75	1	75
HEALTH & PHYSICAL EDUCATION				6,300
Gymnasium		6,000	1	6000
Gym Storeroom		175	1	175
Health Instructor's Office w/ Shower &		125	1	125


MEDIA CENTER				2,800
Media Center / Reading Room		2,800	1	2,800
	1	-		
	\ \ \			
	ł			
ROOM TYPE	1			
DINING & FOOD SERVICE				6,675
Cafeteria / Dining		3,200	1	3200
Stage		1,000	1	1000
Chair / Table / Equipment Storage		375	1	375
Kitchen			1	1600
	1	1,600 250	2	500
Staff Lunch Room (1/3 of staff = 60		230		300
MEDICAL				510
MEDICAL		50		
Medical Suite Toilet		60	1	60
Nurses' Office / Waiting Room		250	1	250
Examination Room / Resting		100	2	200
ADMINISTRATION & GUIDANCE				2450
General Office / Waiting Room / Toilet		675	1	675
Records Room		80	1	80
Principal's Office w/ Conference Area		300	1	300
Assistant Principal's Office		125	1	125
Supervisory/ Itinerant teachers/		650	1	650
Conference Room		200	1	200
Teachers' Work Room		210	2	420
CUSTODIAL & MAINTENANCE				1996
Custodian's Office		150	1	150
Custodian's Workshop		375	1	375
Custodian's Storage		375	1	375
Recycling Room / Trash		400	1	400
Receiving and General Supply	1	232	1	232
Storeroom	1	264	1	264
Network / Telecom Room	1	200	1	200
	1			
Total Building Net Floor Area (NFA)]			52,256
	1			
Proposed Student Capacity / Design	1			
<u> </u>	1			
2	1			78,384
	1			,
Grossing factor (GFA/NFA)				1.50
2 222 3 2222 (2004)				

Existing Condition Study


★ Denotes undersized space

Denotes inaccessible space






Existing Condition Study



Core Academic Spaces Support Spaces Special Education Health & Physical Education Art, Music & Media/ Library Dining & Food Service Performance/ Stage Circulation Toilets, Custodial & MEP





Existing Condition Study

PROS

- Re-use of existing building saves embodied carbon.
- Maintains classic look on street
- Maintains fields during construction
- Maintains relationship of school to neighbors

CONS

- Would require swing space to construct.
- Majority of spaces undersized compared to new program
- Many other important program spaces would not fit.
- Art, Music and Media would stay in basement.
- Pentagon would need to be re-used, but should be torn down.
- Unable to achieve grade level pod configurations.
- Hallways too small to have breakout spaces.
- No room for new lockers in narrow halls.
- Many accessibility issues would be challenging to remedy.