School Building Committee Meeting Franklin Elementary School Study of Options August 11, 2022

HM HMFH ARCHITECTS



Existing Site Plan Study



SITE STATISTICS

5.45 Acre Site 760' Street Frontage **PUB** Zoning

Surrounding Zoning RES3

85.6% Open Space

1* Fields in poor shape. 2* Ramp does not meet current ADA Code



Proposed Program for New Franklin School

	PROPOSED FRANKLIN			
ROOM TYPE		ROOM	# OF	area
CORE ACADEMIC SPACES				21,300
(List classrooms of different sizes				
Pre-Kindergarten w/ toilet				
Kindergarten w/ toilet		1,200	4	4,800
General Classrooms - Grade 1-5		900	18	16,200
ELL Program		300	1	300
SPECIAL ED, RESOURCE & SUPPORT SPACE				7,650
(List rooms of different sizes separately)				
Bridge Program Classroom		900	2	1,800
Bridge Safe Room		100	2	200
Bridge Specialist Office		150	2	300
Bridge Breakout Room		125	2	250
Learning Centers (K-2; 3-5)		450	2	900
Breakout Rooms (small group/ individual		125	6	750
OT/PT		475	1	475
OT/PT Office		150	1	150
Safe Room / Mindful Room (1/ academic		100	2	200
Speech + Language		300	1	300
Inclusion Facilitators (office for 6 adults;		250	1	250
Team Specialist + IEP Conf Room (12		400	1	400
Psychologist (Office, testing, therapy,		150 150	1	150 150
Social Worker (Office, testing,		150	1	150
Reading Program/ Literacy Room		900	1	900
Literacy Specialist Offices		175	1	175
Math Coach		150	1	150
SEL Coach		150	1	150
ART & MUSIC				2,575
Art Classroom - 25 seats		1000	1	1000
Art Workroom w/ Storage & kiln		150	1	150
Music Classroom / Large Group - 25-50		1200	1	1200
Music Practice / Ensemble (Groups 4-		150	1	150
Music Practice / Ensemble (Groups 4-		75	1	75
				6,300
HEALTH & PHYSICAL EDUCATION		6 000	1	
Gymnasium		6,000 175	1	6000 175
Gym Storeroom Health Instructor's Office w/ Shower &		175	1	175
nearth instructor's Office wy Shower &		123	1	123

1EDIA CENTER				2,80
Media Center / Reading Room		2,800	1	2,80
	1			
	1			
ROOM TYPE	1 1			
INING & FOOD SERVICE				6,67
Cafeteria / Dining		3,200	1	320
Stage		1,000	1	100
Chair / Table / Equipment Storage		375	1	37
Kitchen		1,600	1	160
Staff Lunch Room (1/3 of staff = 60		250	2	50
1EDICAL				51
Medical Suite Toilet		60	1	6
Nurses' Office / Waiting Room		250	1	25
Examination Room / Resting		100	2	20
,				
DMINISTRATION & GUIDANCE				245
General Office / Waiting Room / Toilet		675	1	67
Records Room		80	1	8
Principal's Office w/ Conference Area		300	1	30
Assistant Principal's Office		125	1	12
Supervisory/ Itinerant teachers/		650	1	65
Conference Room		200	1	20
Teachers' Work Room		210	2	42
USTODIAL & MAINTENANCE				199
Custodian's Office		150	1	15
Custodian's Workshop		375	1	37
Custodian's Storage		375	1	37
Recycling Room / Trash		400	1	40
Receiving and General Supply		232	1	23
Storeroom		264	1	26
Network / Telecom Room		200	1	20
				-
Total Building Net Floor Area (NFA)				52,25
				,
Proposed Student Capacity / Design				
2				78,38
۷۲				, 0,00
Grossing factor (GFA/NFA)				1.5
				1.5

Pre-feasibility program will be based on the high end enrollment numbers.

Enrollment (TBD):


Low End - 396 students (18+2 CRs) High End - 465 students (22+2 CRs)


Existing Condition Study

★ Denotes undersized space



Denotes inaccessible space






KEY

- Art, Music & Media/ Library Dining & Food Service Performance/ Stage
- Toilets, Custodial & MEP

Existing Condition Study




KEY


Core Academic Spaces Support Spaces Special Education Administration Health & Physical Education

Missing Program Spaces/SF

TOTAL NET SF MISSING: 17,000SF









Art, Music & Media/ Library Dining & Food Service Performance/ Stage Circulation Toilets, Custodial & MEP

CR

S S S

Stage

Existing Condition Study

PROS


- Re-use of existing building saves embodied carbon.
- Maintains classic look on street
- Maintains fields during construction
- Maintains relationship of school to neighbors

CONS

- Would require swing space to construct.
- Majority of spaces undersized compared to new program
- Many other important program spaces would not fit.
- Art, Music and Media would stay in basement.
- Pentagon would need to be re-used, but should be torn down.
- Unable to achieve grade level pod configurations.
- Hallways too small to have breakout spaces.
- No room for new lockers in narrow halls.
- Many accessibility issues would be challenging to remedy.

Addition/ Renovation Studies Matrix






First Floor


Second Floor

Third Floor














2174 168 164 165 165 166 1.18 1.40 2.172 1.20 1.10 1.10



2-174 168 164 158









New Construction Studies Matrix

2.174 .68















82. 474





First Floor


Second Floor


Third Floor



































Add/Reno Option Site Plan

80.2% Open Space







Service Access















Add/Reno Option Elevation



Add/Reno Option Section



Add/ Reno Option

PROS

- Re-use of existing building facade saves some embodied carbon.
- Maintains classic look on street
- Maintains partial fields during construction
- Maintains relationship of school to neighbors
- Classrooms have optimum North/ South solar orientation.
- Entry within the existing facade can present the excitement of the new within the old.

CONS


- Would require swing space to construct.
- Larger footprint on site.
- Less efficient building floor plan.
- Requires ramps to navigate grade change at entry.
- Media center less efficient, requires ramps.
- Entry within existing facade may not meet Newton's Historic Commissions approval.

New Construction Option Site Plan

82% Open Space



New Construction Option First Floor Plan



Ar
Di
Pe
Ci
Тс

Art, Music & Media/ Library
Dining & Food Service
Performance/ Stage
Circulation
Toilets, Custodial & MEP



New Construction Option Second Floor Plan




А	
D	
P	
С	
Тс	

rt, Music & Media/ Library ining & Food Service Performance/ Stage Circulation Toilets, Custodial & MEP



New Construction Option Third Floor Plan




А	
D	
P	
С	
Тс	


rt, Music & Media/ Library Dining & Food Service Performance/ Stage Circulation Toilets, Custodial & MEP



New Construction Option Elevation



New Construction Option Section



4

New Construction Option

PROS

- Eliminates the need for swing space
- Design and construction could start as soon as desired.
- Efficient Floor plan.
- Classrooms are in optimum North/ South solar orientation.
- Grade change from Derby Street to first floor is minimal.
- Students remain in neighborhood school during construction.

CONS


- Students remain on site during construction. Can be loud and safety issues need to be addressed by GC/CM.
- No field space during construction.
- Changes the building's relationship to abutters.

New Construction Option (In same location as existing building) Site Plan



82% Open Space

New Construction Option (In same location as existing building) First Floor Plan



Service Access




New Construction Option (In same location as existing building) Second Floor Plan






New Construction Option (In same location as existing building) Third Floor Plan






New Construction Option (In same location as existing building) Elevation



Main Entry

New Construction Option (In same location as existing building) Section





New Construction Option (In same location as existing building)

PROS

- Maintains partial fields during construction
- Maintains relationship of school to neighbors
- Efficient Floor plan.
- Classrooms are in optimum North/ South solar orientation.

CONS

- Would require swing space to construct.
- Grade change from Derby Street to first floor is significant.