


LEVINGSTON COVE AT CRYSTAL LAKE - SITE ANALYSIS

NEWTON, MA

APRIL 2018






LEVINGSTON COVE AT CRYSTAL LAKE - EXISTING CONDITION

NEWTON, MA

APRIL 2018






LEVINGSTON COVE AT CRYSTAL LAKE - OPPORTUNITIES DIAGRAM


NEWTON, MA

APRIL 2018






SECTION AT FISHING WALL



SECTION AT SHORELINE AREA




LEVINGSTON COVE AT CRYSTAL LAKE - OPTION 1


NEWTON, MA

APRIL 2018







SECTION AT FISHING WALL



SECTION AT SHORELINE AREA




LEVINGSTON COVE AT CRYSTAL LAKE - OPTION 2


NEWTON, MA

APRIL 2018






SECTION AT FISHING WALL



SECTION AT SHORELINE AREA



LEVINGSTON COVE AT CRYSTAL LAKE - OPTION 3

NEWTON, MA

APRIL 2018

