

EXTERIOR



HISTORIC  
PAWT  
COLORS  
BY  
GRETCHEN  
SCHULER

REPAIRS




SHINGLE  
DETAIL





REAR PORCH



EXTERIOR REPAIRS GUTTERS








SINGLE  
DETAIL  
GUTTERS

DOWN  
SPOUTS  
WOOD TRIM  
CLAPBOARDS



HANDICAP  
ACCESSIBILITY





INTERIOR  
LIGHTING



CEILING  
PANELS



CEILING  
PANELS





BATHROOM  
FLOOR

RESTORE PLASTER WALLS







ATTIC  
FLOOR



BASEMENT - ROTTED WOOD



ATTIC  
WINDOW